



This is the building foundation.

These are hanger rods that utility lines hang from to provide buffer from shifting soils and prevent damage.

This area was previously buried, but over the last several months crews have removed soil to create an accessible crawl space and expose utility lines.



Before Excavation



During Excavation



Current