



# Eagan HS Activity Center Construction Update Week of 05.18.26





The underground storm water chamber system install is complete.





The area near the pond is getting prepped for install of a new retaining wall.





Site Utility and New Storm Sewer work on the North side of the school has been installed





Locker room ceiling demolition and joist pocket removal are ongoing in preparation for the new bar joist installation.

