



# Palmer High School

Level: HS · Service Area: Central · IB School · April 2026

## BUILDING INFORMATION

Year Built	Site Area	Building Size	Enrollment	Utilization
1939	14.05 ac	276,689	1,167	73%

## FACILITY CONDITION INDEX & EDUCATIONAL ADEQUACY

### FACILITY CONDITION INDEX (FCI)

**28.8%**

Age/condition-based score. Higher % indicates greater need.

### EDUCATIONAL ADEQUACY (EA)

**46.1%**

Measures how well campus supports 21st century learning. Lower % indicates greater need.

## EDUCATIONAL ADEQUACY — CATEGORY BREAKDOWN

Presence <b>72%</b>	Safety & Security <b>48%</b>
Community <b>61%</b>	Organization <b>25%</b>
Classroom <b>35%</b>	Environmental Quality <b>73%</b>
Assembly <b>44%</b>	Extended Learning <b>11%</b>

## FACILITY CONDITION ASSESSMENT

Building Infrastructure <b>Highest Need</b>	Code / Security <b>Highest Need</b>	Learning Env., Athletics & Arts <b>Highest Need</b>
Site Improvements <b>Fair</b>	Technology Infrastructure <b>Good</b>	Transportation <b>Good</b>