

Inspection and Testing Certificate

Presented To

SAN JUAN USD

For

EARL LEGETTE ELEMENTARY

4623 KENNETH AVE
FAIR OAKS, California 95628
United States

This site has been inspected and tested in compliance with applicable standards.

Completed
Thursday, July 24, 2025

Test Session :22 Jul 2025 07:11 RJ6615 AFA

ACCEPTED BY

SAN JUAN USD
5320 HEMLOCK ST
SACRAMENTO, California
United States

TESTED BY

Riley Goyet
Western States Fire Protection-
Sacramento
188 Cirby Way
Roseville, CA 95678
United States



Inspection Summary

Building Information

PROPERTY	EARL LEGETTE ELEMENTARY	CONTACT
ADDRESS	4623 KENNETH AVE	PHONE
CITY/STATE/ZIP	FAIR OAKS, California 95628	MOBILE
COUNTRY	United States	EMAIL

Inspector Information

COMPANY	Western States Fire Protection-Sacramento	CONTACT	Riley Goyet
ADDRESS	188 Cirby Way Roseville, CA 95678	LICENSE NUMBER	
COUNTRY	United States	PHONE	+1 916-200-9514
		EMAIL	riley.goyet@wsfp.us

Testing Summary

EQUIPMENT TYPE	TOTAL	TESTED	PASSED	FAILED
Initiating Device	204	191(94%)	191(94%)	0(0%)
Fire Control Panel	2	2(100%)	1(50%)	1(50%)
Alarm Notification Appliance	1	1(100%)	1(100%)	0(0%)

Certification

The equipment specified herein was inspected and tested according to the NFPA 72 standard for fire alarm and signaling systems, with the inspection completed on Thursday, July 24, 2025

ACCEPTED BY 07/24/2025

Building Representative


TESTED BY 07/24/2025
Riley Goyet
Technician

System Details

Control Units

ADDRESS / SCAN ADDRESS		DESCRIPTION	FACP E105 Library (2)12v55ah
MANUFACTURER	EST	S/W VERSION	
MODEL	3	LAST UPDATE	
SERIAL NUMBER		S/W LOCATION	
INSTALL DATE			

Open Corrective Action & Solution Summary

The following 1 corrective action(s) remain open following the system inspection, testing or maintenance activities

EQUIPMENT TYPE	ADDRESS	DESCRIPTION
NAC Power Extender Panel	151	BPS-B1 E105 Library (2)12v7ah
	Created By:	Chris Spencer
	Creation Date:	07/22/2025
	Corrective Action:	Both 12v 7ah batteries need replaced
	Proposed Solution:	
	Manufacturer:	
	Model:	

Testing Details

Alarm Notification Appliance

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Horn/Strobe		Horns/Strobes	Manual	7/22/2025 12:48:35 PM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	

Fire Control Panel

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Fire Alarm Panel		FACP E105 Library (2)12v55ah	Manual	7/22/2025 8:51:17 AM
	Comment:	11/22/2024 Left 100% Right 100%		
		Manufacturer	EST	
		Model	3	
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	

Failed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
NAC Power Extender Panel	151	BPS-B1 E105 Library (2)12v7ah	Manual	7/22/2025 8:56:23 AM
	Comment:	Both 12v 7ah batteries over 5 years old (2016)		
		Visual inspection	Failed (Manual)	
		Functional Inspection	Failed	

Initiating Device

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	6.001	Bldg A Boys Restroom	Manual	7/22/2025 10:26:00 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.002	Bldg A Electrical Room	Manual	7/22/2025 9:46:31 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.003	Bldg A Girls Restroom	Manual	7/22/2025 9:46:59 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.384	Bldg A Room 101 Attic	Manual	7/22/2025 11:54:17 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.384(1)	Bldg A Room 101 Attic	Manual	7/22/2025 11:54:20 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.022	Bldg A Room 101 East	Manual	7/22/2025 10:04:43 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.024	Bldg A Room 101 West	Manual	7/22/2025 10:03:56 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.383	Bldg A Room 102 Attic	Manual	7/22/2025 11:54:12 AM
		Visual inspection	Passed (Manual)	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.383(1)	Bldg A Room 102 Attic	Manual	7/22/2025 11:54:15 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.021	Bldg A Room 102 East	Manual	7/22/2025 9:59:34 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.019	Bldg A Room 102 West	Manual	7/22/2025 10:00:57 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.382	Bldg A Room 103 Attic	Manual	7/22/2025 11:54:07 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.382(1)	Bldg A Room 103 Attic	Manual	7/22/2025 11:54:10 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.018	Bldg A Room 103 East	Manual	7/22/2025 9:58:02 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.016	Bldg A Room 103 West	Manual	7/22/2025 10:03:06 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.381	Bldg A Room 104 Attic	Manual	7/22/2025 11:54:03 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.381(1)	Bldg A Room 104 Attic	Manual	7/22/2025 11:54:05 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.015	Bldg A Room 104 East	Manual	7/22/2025 9:57:35 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.013	Bldg A Room 104 West	Manual	7/22/2025 9:57:16 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.380	Bldg A Room 105 Attic	Manual	7/22/2025 11:53:58 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.380(1)	Bldg A Room 105 Attic	Manual	7/22/2025 11:54:00 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.010	Bldg A Room 105 East	Manual	7/22/2025 9:56:23 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	6.012	Bldg A Room 105 West	Manual	7/22/2025 9:56:47 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.379	Bldg A Room 106 Attic	Manual	7/22/2025 11:53:55 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.379(1)	Bldg A Room 106 Attic	Manual	7/22/2025 11:53:57 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	6.007	Bldg A Room 106 East	Manual	7/22/2025 9:56:01 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	6.009	Bldg A Room 106 West	Manual	7/22/2025 9:55:40 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	6.009	Functional Inspection	Passed	
Heat Detector - Restorable Spot	6.378	Bldg A Room 107 Attic	Manual	7/22/2025 11:53:51 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	6.378(1)	Bldg A Room 107 Attic	Manual	7/22/2025 11:53:53 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	6.378(1)	Functional Inspection	Passed	
Smoke Detector - General	6.004	Bldg A Room 107 East	Manual	7/22/2025 9:55:14 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	6.004	Functional Inspection	Passed	
Smoke Detector - General	6.006	Bldg A Room 107 West	Manual	7/22/2025 9:54:51 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	6.006	Functional Inspection	Passed	
Smoke Detector - General	5.026	Bldg B Boys Restroom	Manual	7/22/2025 9:15:46 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	5.026	Functional Inspection	Passed	
Smoke Detector - General	5.025	Bldg B Custodial	Manual	7/22/2025 9:16:21 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	5.025	Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.002	Bldg B Custodial Office Attic	Manual	7/22/2025 11:35:43 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	5.002	Functional Inspection	Passed	
Smoke Detector - General	5.001	Bldg B Electrical Room	Manual	7/22/2025 9:32:57 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	5.001	Functional Inspection	Passed	
Smoke Detector - General	5.024	Bldg B Girls Restroom	Manual	7/22/2025 9:16:52 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	5.024	Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.126	Bldg B Room 101 Attic	Manual	7/22/2025 11:41:35 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	5.126	Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.126(1)	Bldg B Room 101 Attic	Manual	7/22/2025 11:41:37 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	5.126(1)	Functional Inspection	Passed	
Smoke Detector - General	5.021	Bldg B Room 101 East	Manual	7/22/2025 9:17:30 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	5.021	Functional Inspection	Passed	
Smoke Detector - General	5.023	Bldg B Room 101 West	Manual	7/22/2025 9:19:43 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	5.023	Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.127	Bldg B Room 102 Attic	Manual	7/22/2025 11:41:39 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	5.127	Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.127(1)	Bldg B Room 102 Attic	Manual	7/22/2025 11:41:41 AM
		Visual inspection	Passed (Manual)	
Heat Detector - Restorable Spot	5.127(1)	Functional Inspection	Passed	
Smoke Detector - General	5.018	Bldg B Room 102 East	Manual	7/22/2025 9:26:42 AM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.020	Bldg B Room 102 West	Manual	7/22/2025 9:21:40 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.128	Bldg B Room 103 Attic	Manual	7/22/2025 11:41:43 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.128(1)	Bldg B Room 103 Attic	Manual	7/22/2025 11:41:46 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.015	Bldg B Room 103 East	Manual	7/22/2025 9:27:06 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.017	Bldg B Room 103 West	Manual	7/22/2025 9:27:29 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.129	Bldg B Room 104 Attic	Manual	7/22/2025 11:41:49 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.129(1)	Bldg B Room 104 Attic	Manual	7/22/2025 11:41:51 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.012	Bldg B Room 104 East	Manual	7/22/2025 9:27:54 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.014	Bldg B Room 104 West	Manual	7/22/2025 9:32:25 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.130	Bldg B Room 105 Attic	Manual	7/22/2025 11:41:55 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.130(1)	Bldg B Room 105 Attic	Manual	7/22/2025 11:41:57 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.009	Bldg B Room 105 East	Manual	7/22/2025 9:28:55 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.011	Bldg B Room 105 West	Manual	7/22/2025 9:29:40 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.131	Bldg B Room 106 Attic	Manual	7/22/2025 11:41:59 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.131(1)	Bldg B Room 106 Attic	Manual	7/22/2025 11:42:01 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.006	Bldg B Room 106 East	Manual	7/22/2025 9:30:20 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	5.008	Bldg B Room 106 West	Manual	7/22/2025 9:31:34 AM
		Visual inspection	Passed (Manual)	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.132	Bldg B Room 107 Attic	Manual	7/22/2025 11:42:03 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	5.132(1)	Bldg B Room 107 Attic	Manual	7/22/2025 11:42:05 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	4.378(1)	Bldg C Room 101 Attic	Manual	7/22/2025 11:28:09 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	4.378	Bldg C Room 101 Attic	Manual	7/22/2025 11:28:11 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	4.008	Bldg C Room 101 East	Manual	7/22/2025 9:08:03 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	4.010	Bldg C Room 101 West	Manual	7/22/2025 7:56:37 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	4.379(1)	Bldg C Room 102 Attic	Manual	7/22/2025 11:27:11 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	4.379	Bldg C Room 102 Attic	Manual	7/22/2025 11:27:15 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	4.005	Bldg C Room 102 East	Manual	7/22/2025 7:55:34 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	4.007	Bldg C Room 102 West	Manual	7/22/2025 7:55:32 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	4.380(1)	Bldg C Room 103 Attic	Manual	7/22/2025 11:25:42 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	4.380	Bldg C Room 103 Attic	Manual	7/22/2025 11:25:46 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	4.002	Bldg C Room 103 East	Manual	7/22/2025 7:48:31 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	4.004	Bldg C Room 103 West	Manual	7/22/2025 7:49:17 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	1.139	Bldg E Faculty Attic	Manual	7/22/2025 11:58:29 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	1.139(1)	Bldg E Faculty Attic	Manual	7/22/2025 11:58:31 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.005	Bldg E Faculty East	Manual	7/22/2025 9:53:03 AM
		Visual inspection	Passed (Manual)	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	Passed	
Smoke Detector - General	1.006	Bldg E Faculty West	Manual	7/22/2025 9:52:43 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.008	Bldg E Library NE	Manual	7/22/2025 9:48:31 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.015	Bldg E Library North Entry	Manual	7/22/2025 9:47:29 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.007	Bldg E Library NW	Manual	7/22/2025 9:48:51 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.009	Bldg E Library SE	Manual	7/22/2025 9:49:10 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.010	Bldg E Library SW	Manual	7/22/2025 9:49:40 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.016	Bldg E North Classroom	Manual	7/22/2025 9:45:07 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.003	Bldg E Restroom	Manual	7/22/2025 9:51:49 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.012	Bldg E Room 101.1	Manual	7/22/2025 9:50:15 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.013	Bldg E Room 101.2	Manual	7/22/2025 9:50:52 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.014	Bldg E Room 101.3	Manual	7/22/2025 9:47:56 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.011	Bldg E Room 102.1	Manual	7/22/2025 9:45:43 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.001	Bldg E Room 106	Manual	7/22/2025 9:51:21 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.018	Bldg E South Classroom	Manual	7/22/2025 9:44:42 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	1.004	Bldg E Staff Restroom	Manual	7/22/2025 9:53:27 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	2.001	Bldg K Electrical Room	Manual	7/22/2025 9:54:10 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Supervisory - Control Valve	2.389	Bldg K PIV	Manual	7/22/2025 12:30:49 PM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Mechanical, Electrosonic, or Pressure Waterflow Device	2.376	Bldg K Riser Room Waterflow	Manual	7/22/2025 12:30:00 PM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	2.005	Bldg K Room 101 North	Manual	7/22/2025 10:16:04 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.003	Bldg K Room 101 South	Manual	7/22/2025 10:16:24 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.026	Bldg K Room 102 North	Manual	7/22/2025 10:17:11 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.028	Bldg K Room 102 South	Manual	7/22/2025 10:16:46 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.023	Bldg K Room 103 Center	Manual	7/22/2025 10:18:13 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.022	Bldg K Room 103 North	Manual	7/22/2025 10:18:38 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.006	Bldg K Room 103 Restroom	Manual	7/22/2025 10:19:10 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.032	Bldg K Room 103 West	Manual	7/22/2025 10:17:53 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.020	Bldg K Room 104 Center	Manual	7/22/2025 10:20:24 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.018	Bldg K Room 104 North	Manual	7/22/2025 10:20:44 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.007	Bldg K Room 104 Restroom	Manual	7/22/2025 10:21:53 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.021	Bldg K Room 104 South	Manual	7/22/2025 10:20:01 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.031	Bldg K Room 104 West	Manual	7/22/2025 10:19:35 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.015	Bldg K Room 105 Center	Manual	7/22/2025 10:21:27 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.014	Bldg K Room 105 North	Manual	7/22/2025 10:22:43 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.008	Bldg K Room 105 Restroom	Manual	7/22/2025 10:23:14 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.017	Bldg K Room 105 South	Manual	7/22/2025 10:21:03 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.030	Bldg K Room 105 West	Manual	7/22/2025 10:22:17 AM
		Visual inspection	Passed (Manual)	
Smoke Detector - General	2.012	Bldg K Room 106 Center	Manual	7/22/2025 10:23:54 AM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	2.010	Bldg K Room 106 North	Manual	7/22/2025 10:24:40 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	2.009	Bldg K Room 106 Restroom	Manual	7/22/2025 10:25:20 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	2.013	Bldg K Room 106 South	Manual	7/22/2025 10:23:34 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	2.029	Bldg K Room 106 West	Manual	7/22/2025 10:24:16 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.005	Bldg L Conference Room 112	Manual	7/22/2025 9:34:17 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.004	Bldg L Counselor Room 111	Manual	7/22/2025 9:35:05 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.001	Bldg L Electrical Room	Manual	7/22/2025 9:38:57 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.006	Bldg L Hallway North	Manual	7/22/2025 9:33:46 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.007	Bldg L Hallway South	Manual	7/22/2025 9:35:35 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.012	Bldg L Health Room 104	Manual	7/22/2025 9:41:27 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.017	Bldg L Principal Room 103	Manual	7/22/2025 9:40:53 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	3.137	Bldg L Reception 101 Attic	Manual	7/22/2025 11:47:13 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.014	Bldg L Reception East Room 101	Manual	7/22/2025 9:42:27 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.013	Bldg L Reception North Room 101	Manual	7/22/2025 9:43:46 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.016	Bldg L Reception West Room 101	Manual	7/22/2025 9:42:05 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.015	Bldg L Secretary Room 102	Manual	7/22/2025 9:43:17 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.003	Bldg L Speech Room 110	Manual	7/22/2025 9:37:48 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.008	Bldg L Staff Restroom 108	Manual	7/22/2025 9:39:27 AM
		Visual inspection	Passed (Manual)	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	Passed	
Smoke Detector - General	3.018	Bldg L Storage Hall	Manual	7/22/2025 9:39:54 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.009	Bldg L Storage Room 106	Manual	7/22/2025 9:40:20 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	3.002	Bldg L Work Room 109	Manual	7/22/2025 9:38:16 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.024	Bldg M Boys Restroom	Manual	7/22/2025 10:08:12 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - Projected Beam	7.145	Bldg M Center Gym Beam	Manual	7/22/2025 10:29:32 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.021	Bldg M Custodial	Manual	7/22/2025 10:05:22 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.017	Bldg M Dry Storage	Manual	7/22/2025 10:14:37 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.002	Bldg M Electrical Room	Manual	7/22/2025 10:12:38 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.023	Bldg M Girls Restroom	Manual	7/22/2025 10:07:47 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	7.015	Bldg M Kitchen Center	Manual	7/22/2025 11:57:08 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.019	Bldg M Kitchen Custodial	Manual	7/22/2025 10:13:38 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	7.014	Bldg M Kitchen North	Manual	7/22/2025 11:57:05 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	7.016	Bldg M Kitchen South	Manual	7/22/2025 11:57:03 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Duct Detector	7.137	Bldg M MAU1 (Kitchen)	Manual	7/22/2025 10:33:55 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - Projected Beam	7.143	Bldg M North Gym Beam	Manual	7/22/2025 10:28:05 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.013	Bldg M Office	Manual	7/22/2025 10:13:07 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Supervisory - Control Valve	7.126	Bldg M PIV	Manual	7/22/2025 12:44:25 PM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.018	Bldg M Restroom	Manual	7/22/2025 10:14:10 AM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Mechanical, Electrosonic, or Pressure Waterflow Device	7.128	Bldg M Riser Room Waterflow	Manual	7/22/2025 12:30:06 PM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Manual Pull Station	7.156	Bldg M SE Gym Entry	Manual	7/22/2025 12:45:17 PM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - Projected Beam	7.141	Bldg M South Gym Beam	Manual	7/22/2025 10:27:31 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.022	Bldg M Staff Restroom	Manual	7/22/2025 10:06:14 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.009	Bldg M Stage East	Manual	7/22/2025 10:10:06 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.004	Bldg M Stage NW	Manual	7/22/2025 10:11:21 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.011	Bldg M Stage Storage	Manual	7/22/2025 10:10:52 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.012	Bldg M Stage SW	Manual	7/22/2025 10:09:41 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.010	Bldg M Stage West	Manual	7/22/2025 10:10:28 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.007	Bldg M Storage East	Manual	7/22/2025 10:09:15 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.008	Bldg M Storage West	Manual	7/22/2025 10:08:55 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.003	Bldg M Vestibule	Manual	7/22/2025 10:11:49 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Smoke Detector - General	7.020	Bldg M West Hall	Manual	7/22/2025 10:05:46 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	8.389	Classroom 25 Attic	Manual	7/22/2025 11:32:42 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	8.389(1)	Classroom 25 Attic	Manual	7/22/2025 11:32:45 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	8.388	Classroom 26 Attic	Manual	7/22/2025 11:32:36 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	
Heat Detector - Restorable Spot	8.388(1)	Classroom 26 Attic	Manual	7/22/2025 11:32:40 AM
		Visual inspection	Passed (Manual)	
		Functional Inspection	Passed	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Heat Detector - Restorable Spot	8.387	Classroom 27 Attic	Manual	7/22/2025 11:32:32 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.387(1)	Classroom 27 Attic	Manual	7/22/2025 11:32:34 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.386	Classroom 28 Attic	Manual	7/22/2025 11:32:26 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.386(1)	Classroom 28 Attic	Manual	7/22/2025 11:32:28 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.385	Classroom 29 Attic	Manual	7/22/2025 11:33:55 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.385(1)	Classroom 29 Attic	Manual	7/22/2025 11:33:58 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.251	Room 23	Manual	7/22/2025 7:56:41 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.252	Room 23	Manual	7/22/2025 9:09:47 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.376	Room 23 Attic	Manual	7/22/2025 11:32:19 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.376(1)	Room 23 Attic	Manual	7/22/2025 11:32:21 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.254	Room 24	Manual	7/22/2025 9:10:47 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.253	Room 24	Manual	7/22/2025 9:11:06 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.377	Room 24 Attic	Manual	7/22/2025 11:32:23 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Heat Detector - Restorable Spot	8.377(1)	Room 24 Attic	Manual	7/22/2025 11:32:25 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.257	Room 25	Manual	7/22/2025 9:11:25 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.259	Room 25	Manual	7/22/2025 9:11:41 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.260	Room 26	Manual	7/22/2025 9:12:03 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	8.258	Room 26	Manual	7/22/2025 9:12:25 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.256	Room 27	Manual	7/22/2025 9:12:50 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.262	Room 27	Manual	7/22/2025 9:13:14 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.261	Room 28	Manual	7/22/2025 9:13:56 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.263	Room 28	Manual	7/22/2025 9:14:13 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.264	Room 29	Manual	7/22/2025 9:14:38 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	
Smoke Detector - General	8.255	Room 29	Manual	7/22/2025 9:15:02 AM
		Visual inspection Functional Inspection	Passed (Manual) Passed	

Skipped

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Heat Detector - Restorable Spot	1.141	Bldg E Library Center Attic	Manual	7/22/2025 12:20:03 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.141(1)	Bldg E Library Center Attic	Manual	7/22/2025 12:20:11 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.141(2)	Bldg E Library Center Attic	Manual	7/22/2025 12:20:21 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.140	Bldg E Library East Attic	Manual	7/22/2025 12:17:03 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.140(1)	Bldg E Library East Attic	Manual	7/22/2025 12:18:40 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.140(2)	Bldg E Library East Attic	Manual	7/22/2025 12:19:49 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.142	Bldg E Library West Attic	Manual	7/22/2025 12:20:33 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.142(1)	Bldg E Library West Attic	Manual	7/22/2025 12:20:40 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	1.142(2)	Bldg E Library West Attic	Manual	7/22/2025 12:20:55 PM
		Comment:	No access to attic heat 15'+ feet	
Heat Detector - Restorable Spot	3.131	Bldg L Conference Room 112	Manual	7/22/2025 12:27:08 PM
		Comment:	No access to heat ductwork in the way	
Heat Detector - Restorable Spot	3.132	Bldg L Hallway	Manual	7/22/2025 12:27:39 PM
		Comment:	No access to heat ductwork in the way	
Heat Detector - Restorable Spot	3.136	Bldg L Health 104	Manual	7/22/2025 12:27:51 PM
		Comment:	No access to heat ductwork in the way	
Heat Detector - Restorable Spot	3.139	Bldg L Principal 103	Manual	7/22/2025 12:26:15 PM
		Comment:	No access to heat ductwork in the way	

Device/Equipment Details

Alarm Notification Appliance

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
Horn/Strobe					
	Horns/Strobes				07/22/2025

Fire Control Panel

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
NAC Power Extender Panel					
151	BPS-B1 E105 Library (2)12v7ah				
Fire Alarm Panel					
	FACP E105 Library (2)12v55ah	EST		3	

Initiating Device

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
Smoke Detector - General					
4.002	Bldg C Room 103 East				07/22/2025
4.004	Bldg C Room 103 West				07/22/2025
4.005	Bldg C Room 102 East				07/22/2025
4.007	Bldg C Room 102 West				07/22/2025
4.010	Bldg C Room 101 West				07/22/2025
8.251	Room 23				07/22/2025
4.008	Bldg C Room 101 East				07/22/2025
8.252	Room 23				07/22/2025
8.254	Room 24				07/22/2025
8.253	Room 24				07/22/2025
8.257	Room 25				07/22/2025
8.259	Room 25				07/22/2025
8.260	Room 26				07/22/2025
8.258	Room 26				07/22/2025
8.256	Room 27				07/22/2025
8.262	Room 27				07/22/2025
8.261	Room 28				07/22/2025
8.263	Room 28				07/22/2025
8.264	Room 29				07/22/2025
8.255	Room 29				07/22/2025
5.026	Bldg B Boys Restroom				07/22/2025
5.025	Bldg B Custodial				07/22/2025
5.024	Bldg B Girls Restroom				07/22/2025
5.021	Bldg B Room 101 East				07/22/2025
5.023	Bldg B Room 101 West				07/22/2025
5.020	Bldg B Room 102 West				07/22/2025
5.018	Bldg B Room 102 East				07/22/2025
5.015	Bldg B Room 103 East				07/22/2025
5.017	Bldg B Room 103 West				07/22/2025
5.012	Bldg B Room 104 East				07/22/2025
5.009	Bldg B Room 105 East				07/22/2025
5.011	Bldg B Room 105 West				07/22/2025
5.006	Bldg B Room 106 East				07/22/2025
5.008	Bldg B Room 106 West				07/22/2025
5.014	Bldg B Room 104 West				07/22/2025
5.001	Bldg B Electrical Room				07/22/2025
3.006	Bldg L Hallway North				07/22/2025

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
3.005	Bldg L Conference Room 112				07/22/2025
3.004	Bldg L Counselor Room 111				07/22/2025
3.007	Bldg L Hallway South				07/22/2025
3.003	Bldg L Speech Room 110				07/22/2025
3.002	Bldg L Work Room 109				07/22/2025
3.001	Bldg L Electrical Room				07/22/2025
3.008	Bldg L Staff Restroom 108				07/22/2025
3.018	Bldg L Storage Hall				07/22/2025
3.009	Bldg L Storage Room 106				07/22/2025
3.017	Bldg L Principal Room 103				07/22/2025
3.012	Bldg L Health Room 104				07/22/2025
3.016	Bldg L Reception West Room 101				07/22/2025
3.014	Bldg L Reception East Room 101				07/22/2025
3.015	Bldg L Secretary Room 102				07/22/2025
3.013	Bldg L Reception North Room 101				07/22/2025
1.018	Bldg E South Classroom				07/22/2025
1.016	Bldg E North Classroom				07/22/2025
1.011	Bldg E Room 102.1				07/22/2025
6.002	Bldg A Electrical Room				07/22/2025
6.003	Bldg A Girls Restroom				07/22/2025
1.015	Bldg E Library North Entry				07/22/2025
1.014	Bldg E Room 101.3				07/22/2025
1.008	Bldg E Library NE				07/22/2025
1.007	Bldg E Library NW				07/22/2025
1.009	Bldg E Library SE				07/22/2025
1.010	Bldg E Library SW				07/22/2025
1.012	Bldg E Room 101.1				07/22/2025
1.013	Bldg E Room 101.2				07/22/2025
1.001	Bldg E Room 106				07/22/2025
1.003	Bldg E Restroom				07/22/2025
1.006	Bldg E Faculty West				07/22/2025
1.005	Bldg E Faculty East				07/22/2025
1.004	Bldg E Staff Restroom				07/22/2025
2.001	Bldg K Electrical Room				07/22/2025
6.006	Bldg A Room 107 West				07/22/2025
6.004	Bldg A Room 107 East				07/22/2025
6.009	Bldg A Room 106 West				07/22/2025
6.007	Bldg A Room 106 East				07/22/2025
6.010	Bldg A Room 105 East				07/22/2025
6.012	Bldg A Room 105 West				07/22/2025
6.013	Bldg A Room 104 West				07/22/2025
6.015	Bldg A Room 104 East				07/22/2025
6.018	Bldg A Room 103 East				07/22/2025
6.021	Bldg A Room 102 East				07/22/2025
6.019	Bldg A Room 102 West				07/22/2025
6.016	Bldg A Room 103 West				07/22/2025
6.024	Bldg A Room 101 West				07/22/2025
6.022	Bldg A Room 101 East				07/22/2025
7.021	Bldg M Custodial				07/22/2025
7.020	Bldg M West Hall				07/22/2025
7.022	Bldg M Staff Restroom				07/22/2025

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
7.023	Bldg M Girls Restroom				07/22/2025
7.024	Bldg M Boys Restroom				07/22/2025
7.008	Bldg M Storage West				07/22/2025
7.007	Bldg M Storage East				07/22/2025
7.012	Bldg M Stage SW				07/22/2025
7.009	Bldg M Stage East				07/22/2025
7.010	Bldg M Stage West				07/22/2025
7.011	Bldg M Stage Storage				07/22/2025
7.004	Bldg M Stage NW				07/22/2025
7.003	Bldg M Vestibule				07/22/2025
7.002	Bldg M Electrical Room				07/22/2025
7.013	Bldg M Office				07/22/2025
7.019	Bldg M Kitchen Custodial				07/22/2025
7.018	Bldg M Restroom				07/22/2025
7.017	Bldg M Dry Storage				07/22/2025
2.005	Bldg K Room 101 North				07/22/2025
2.003	Bldg K Room 101 South				07/22/2025
2.028	Bldg K Room 102 South				07/22/2025
2.026	Bldg K Room 102 North				07/22/2025
2.032	Bldg K Room 103 West				07/22/2025
2.023	Bldg K Room 103 Center				07/22/2025
2.022	Bldg K Room 103 North				07/22/2025
2.006	Bldg K Room 103 Restroom				07/22/2025
2.031	Bldg K Room 104 West				07/22/2025
2.021	Bldg K Room 104 South				07/22/2025
2.020	Bldg K Room 104 Center				07/22/2025
2.018	Bldg K Room 104 North				07/22/2025
2.017	Bldg K Room 105 South				07/22/2025
2.015	Bldg K Room 105 Center				07/22/2025
2.007	Bldg K Room 104 Restroom				07/22/2025
2.030	Bldg K Room 105 West				07/22/2025
2.014	Bldg K Room 105 North				07/22/2025
2.008	Bldg K Room 105 Restroom				07/22/2025
2.013	Bldg K Room 106 South				07/22/2025
2.012	Bldg K Room 106 Center				07/22/2025
2.029	Bldg K Room 106 West				07/22/2025
2.010	Bldg K Room 106 North				07/22/2025
2.009	Bldg K Room 106 Restroom				07/22/2025
6.001	Bldg A Boys Restroom				07/22/2025
Smoke Detector - Projected Beam					
7.141	Bldg M South Gym Beam				07/22/2025
7.143	Bldg M North Gym Beam				07/22/2025
7.145	Bldg M Center Gym Beam				07/22/2025
Duct Detector					
7.137	Bldg M MAU1 (Kitchen)				07/22/2025
Heat Detector - Restorable Spot					
4.380	Bldg C Room 103 Attic				07/22/2025
4.380(1)	Bldg C Room 103 Attic				07/22/2025
4.379	Bldg C Room 102 Attic				07/22/2025
4.379(1)	Bldg C Room 102 Attic				07/22/2025
4.378	Bldg C Room 101 Attic				07/22/2025
4.378(1)	Bldg C Room 101 Attic				07/22/2025

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
8.376	Room 23 Attic				07/22/2025
8.376(1)	Room 23 Attic				07/22/2025
8.377	Room 24 Attic				07/22/2025
8.377(1)	Room 24 Attic				07/22/2025
8.389	Classroom 25 Attic				07/22/2025
8.389(1)	Classroom 25 Attic				07/22/2025
8.388	Classroom 26 Attic				07/22/2025
8.388(1)	Classroom 26 Attic				07/22/2025
8.387	Classroom 27 Attic				07/22/2025
8.387(1)	Classroom 27 Attic				07/22/2025
8.386	Classroom 28 Attic				07/22/2025
8.386(1)	Classroom 28 Attic				07/22/2025
8.385	Classroom 29 Attic				07/22/2025
8.385(1)	Classroom 29 Attic				07/22/2025
5.002	Bldg B Custodial Office Attic				07/22/2025
5.126	Bldg B Room 101 Attic				07/22/2025
5.126(1)	Bldg B Room 101 Attic				07/22/2025
5.127	Bldg B Room 102 Attic				07/22/2025
5.127(1)	Bldg B Room 102 Attic				07/22/2025
5.128	Bldg B Room 103 Attic				07/22/2025
5.128(1)	Bldg B Room 103 Attic				07/22/2025
5.129	Bldg B Room 104 Attic				07/22/2025
5.129(1)	Bldg B Room 104 Attic				07/22/2025
5.130	Bldg B Room 105 Attic				07/22/2025
5.130(1)	Bldg B Room 105 Attic				07/22/2025
5.131	Bldg B Room 106 Attic				07/22/2025
5.131(1)	Bldg B Room 106 Attic				07/22/2025
5.132	Bldg B Room 107 Attic				07/22/2025
5.132(1)	Bldg B Room 107 Attic				07/22/2025
3.137	Bldg L Reception 101 Attic				07/22/2025
6.378	Bldg A Room 107 Attic				07/22/2025
6.378(1)	Bldg A Room 107 Attic				07/22/2025
6.379	Bldg A Room 106 Attic				07/22/2025
6.379(1)	Bldg A Room 106 Attic				07/22/2025
6.380	Bldg A Room 105 Attic				07/22/2025
6.380(1)	Bldg A Room 105 Attic				07/22/2025
6.381	Bldg A Room 104 Attic				07/22/2025
6.381(1)	Bldg A Room 104 Attic				07/22/2025
6.382	Bldg A Room 103 Attic				07/22/2025
6.382(1)	Bldg A Room 103 Attic				07/22/2025
6.383	Bldg A Room 102 Attic				07/22/2025
6.383(1)	Bldg A Room 102 Attic				07/22/2025
6.384	Bldg A Room 101 Attic				07/22/2025
6.384(1)	Bldg A Room 101 Attic				07/22/2025
7.016	Bldg M Kitchen South				07/22/2025
7.015	Bldg M Kitchen Center				07/22/2025
7.014	Bldg M Kitchen North				07/22/2025
1.139	Bldg E Faculty Attic				07/22/2025
1.139(1)	Bldg E Faculty Attic				07/22/2025
1.140	Bldg E Library East Attic				07/22/2025
1.140(1)	Bldg E Library East Attic				07/22/2025
1.140(2)	Bldg E Library East Attic				07/22/2025

ADDRESS	DESCRIPTION	MANUFACTURER	MODEL	SERIAL	INSTALL DATE
1.141	Bldg E Library Center Attic				07/22/2025
1.141(1)	Bldg E Library Center Attic				07/22/2025
1.141(2)	Bldg E Library Center Attic				07/22/2025
1.142	Bldg E Library West Attic				07/22/2025
1.142(1)	Bldg E Library West Attic				07/22/2025
1.142(2)	Bldg E Library West Attic				07/22/2025
3.132	Bldg L Hallway				07/22/2025
3.131	Bldg L Conference Room 112				07/22/2025
3.139	Bldg L Principal 103				07/22/2025
3.136	Bldg L Health 104				07/22/2025
Mechanical, Electrosonic, or Pressure Waterflow Device					
2.376	Bldg K Riser Room Waterflow				07/22/2025
7.128	Bldg M Riser Room Waterflow				07/22/2025
Supervisory - Control Valve					
2.389	Bldg K PIV				07/22/2025
7.126	Bldg M PIV				07/22/2025
Manual Pull Station					
7.156	Bldg M SE Gym Entry				07/22/2025