

2026								
Sample ID	Sampler	Sample Date	Sample Time	School	Location	Copper Result	Lead Result	Repairs Needed
HS-1	D.B.	5/18/2026	5:15am	High School	Ag Shop Sink	0.313	0.005	N/A
HS-2	D.B.	5/18/2026	5:17am	High School	Water cooler fill closet near pool	0.259	0.004	N/A
HS-3	D.B.	5/18/2026	5:20am	High School	3rd floor boys restroom sink (west side)	0.247	0.005	N/A
MS-1	D.B.	5/18/2026	4:55am	Middle School	Maintenance office sink	0.202	0.002	N/A
MS-2	D.B.	5/18/2026	5:00am	Middle School	Commons bottle filling station	0.055	<0.001	N/A
MS-3	D.B.	5/18/2026	5:05am	Middle School	7th grade boys restroom sink	0.157	0.007	N/A
MR-1	D.B.	5/18/2026	5:25am	Mount Rock	Fitness Center bottle filling station	0.099	<0.001	N/A
MR-2	D.B.	5/18/2026	5:27am	Mount Rock	Kitchen prep sink	0.238	0.001	N/A
MR-3	D.B.	5/18/2026	5:30am	Mount Rock	Upstairs Boys Restroom sink	0.156	<0.001	N/A
NV-1	D.B.	5/18/2026	6:15am	Newville	Gym Water Bottle filling station	0.057	<0.001	N/A
NV-2	D.B.	5/18/2026	6:17am	Newville	1st floor Boys restroom sink (near main office)	0.237	0.002	N/A
NV-3	D.B.	5/18/2026	6:20am	Newville	2nd floor bathroom (east wing)	0.233	<0.001	N/A
OF-1	D.B.	5/18/2026	5:40am	Oak Flat	Custodial closet sink at dock	0.201	0.005	N/A
OF-2	D.B.	5/18/2026	5:45am	Oak Flat	Water fountain near main office lobby	0.184	<0.001	N/A
OF-3	D.B.	5/18/2026	5:50am	Oak Flat	2nd Floor boys restroom sink	0.211	<0.001	N/A
DO-1	D.B.	5/18/2026	6:00am	District Office	Kitchen Sink	0.222	0.003	N/A
DO-2	D.B.	5/18/2026	6:02am	District Office	Entrance Foyer water fountain	0.092	<0.001	N/A