Kyrene de la Mirada Flood

June 23, 2026

Emergency Response Timeline

Incident

- Emergency Management Team (EMT) notified June 15 at approximately 7:30 a.m.
- Initial damage assessed

Response

- Team meeting convened at 8:00 a.m.
- Remediation plan discussed
- Options considered:
  - Repairs
  - Portables
  - Relocation

Closure

- EMT determined that the best option would be to close the campus and relocate to Kyrene de las Manitas

Damage and Remediation

Incident Summary

- Domestic water line failure within wall cavity
- Facilities notified June 15, 2026, at approximately 7:30 a.m.
- Flood damage to front office and Pod A
- Remediation contractor mobilized within one hour
- Immediate water extraction and drying operations initiated
- Notified the Trust (Kyrene insurance provider)

Key Response Actions

- Water extraction completed
- Air movers and dehumidifiers deployed
- All environmental testing results, remediation recommendations, and restoration scope decisions are reviewed and approved by The Trust before work progresses to the next phase.
- Environmental testing completed and provided to the Trust
    - No asbestos-containing materials (ACM) detected
- Restoration contractor approved by The Trust to start demo and accelerate drying

Remediation Progress

Ongoing Response

- Containment established throughout affected areas
- Cove base removal and wall drying operations ongoing
- Cabinet and countertop removal underway in Pod A
- Approximately 90% of contents relocated and inventoried
- Furniture and contents staged, documented, and categorized as reusable or total loss
- Humidity levels significantly reduced through ongoing drying operations

Next Steps

- Complete contents relocation and cabinet removal
- Electrical inspection of floor outlets and conduits
- Evaluate flooring replacement options in coordination with planned flooring upgrades
- Complete environmental clearance testing
- Develop repair and restoration schedule for reoccupancy
- Coordinate relocation (room identification, furniture assessment, classroom setup).

Damage and Remediation

Communications

June 15

- Staff email and text + follow up from Principal Anderson
- Family email and text*
- Information posted on www.kyrene.org/911

June 18

- Dedicated web page launch: www.kyrene.org/MiradaFlooding
  - communications, remediation efforts, photos
  - expand to include test results, FAQs, progress reports
- Follow up email to families and staff

Upcoming/Ongoing

- NextDoor post to alert Manitas neighbors
- School communications
- Updates on remediation progress
- Two-way communication via OnFlo (Let's Talk)

**Messages included both Mirada and Manitas communities*

**New families received communication on June 17*

Supports for Continuity of Learning

Staff

- Classroom assignments finalized
- Furniture, technology, curriculum, and instructional materials relocation and set up underway
- Access, keys, technology, and operational needs to be addressed prior to opening

Families

- Special education, speech, counseling, and related services maintained
- After school programs will be offered at Manitas (Kids Club, Youth Enrichment, etc.)

All

- Ongoing communication and support from District and site leadership

Next Steps

Coordination and Logistics

- Moving staff and supplies to Manitas campus
- Transportation routing and communication
- Pick up/Drop off and other campus procedures

Timeline for Return

- Students and staff should prepare to be on the Manitas campus through winter break
- Campus may open sooner, depending on progress of repairs and remediation

Communications

- Mirada Back-to-School communications
- District updates via email, text, website and board presentations