

General Information and Fire/Life Safety History

Inspection Date:12/17/25

1. Primary Use:INSTRUCTIONAL

2. Fire Sprinkler System?No

2a. Sprinkler alarm?No

3. Fire Hydrant System?Yes

3a. Hydrant Ownership:Public owned

4. Building Ownership:Owned

5. Leased To Others?:No

6. Square footage:124430

8a. Fire drill manuals distributed?Yes

8d. Average evacuation time:2 minutes 30 seconds

8e. Arson/Fire Prevention?Yes

8f. Prevention/Evacuation Training?Yes

9. Fire Dept. notified via alarm?Yes

10. Any Fires?No

10a. Number of fires:Not Applicable

10b. Number of injuries:Not Applicable

10c. Cost of Damage:Not Applicable

Inspector Notified of previous fire report?Yes

FIRE & EMERGENCY DRILLS

	Date	Type
1	Sep 12, 2024	Evacuation
2	Sep 13, 2024	Evacuation
3	Sep 24, 2024	Evacuation
4	Sep 27, 2024	Evacuation

	Date	Type
5	Oct 4, 2024	Evacuation
6	Oct 10, 2024	Lockdown
7	Oct 24, 2024	Evacuation
8	Nov 21, 2024	Lockdown
9	Feb 4, 2025	Lockdown
10	Mar 19, 2025	Lockdown
11	May 27, 2025	Evacuation
12	Jun 6, 2025	Evacuation

Initial Inspector

Marcie Stiner

Phone #: (Phone Number) (585) 346-4105

Certification #: (Certification Number) 1000-7148B

Email: mstiner@gvboces.org

Building Administrator

Matthew Buisch

Phone #: (Phone Number) (315) 694-1663

Email: mbuisch@romuluscsd.org

Building Overview

ID:
560603040002

District Location:
ROMULUS CSD

Building Type:
INSTRUCTIONAL

Name & Address:
ROMULUS CENTRAL SCHOOL
MAIN STREET
ROMULUS, NY 14541

Inspection History

Date Created:
Jan 29, 2026

Created By:

matthew.buisch

Date Modified:
Jan 30, 2026

Modified By:
jennifer.hayden3

Date Certified:
Jan 30, 2026

Certified By:
jennifer.hayden3

Certificate History

Certificate Type	Date Certified	Certified By
Certificate of Occupancy	Jan 30, 2026	jennifer.hayden3

Non-conformances

Item	Date Corrected	Date Reinspected
09A-2	Dec 22, 2025	
13B-2	Dec 22, 2025	
12E-1	Dec 19, 2025	
02D-1	Dec 17, 2025	
15A-2	Dec 19, 2025	
15D-2	Dec 19, 2025	