



Description

Field: Top soil/existing grass field removed




Description

Classroom 110: Millwork demolished, ceiling grid & tile removed, flooring removed



Description

Corridor 1001: Ceiling panels removed, walls demoed




Description

Media Room and Offices: Walls demoed, ceiling grid and tile removed, flooring removed. Electrical and Mechanical removal on going.



Description

Media: Abatement process completed




Description

Media: MEP make safe complete, prior to demolition




Description

Media: Existing trunk line ductwork removed due to sizing needed for new linear slot diffusers



Description

Field: Existing turf, and grass field removed. Top soil haul off on going



Description



Description

Lower Field: Existing turf relocated to lower field, per request from school