


Description




Description

Corridor 1001: Demolition complete, mechanical rough in on going, wall framing on going



Description

IT/Green Room: Wall framing on going




Description

Media/Commons: Storefront blocking installed, demolition complete, new opening cut in



Description

Corridor 1000: Existing cables secured per fire marshal request




Description

Corridor 1000: Wall demoed for new fire rated windows and wall, ACT and grid removed, cables secured.



Description

Admin Hallway: ACT and grid demoed, cables secured



Description

Field: Subgrade proof roll complete



Description

Field: Drainage System installation on going



Description

Field: Top soil hauled off, subgrade proof rolled