Paul Laurence Dunbar High School – Roof Replacement

- **Completed/Work in Progress:**
  - Work is underway over final sections of area B.
  - High wall flashing is being installed.
  - Alternate staging and debris removal area has been set up on north side of building.
  - Good daily progress of 18-20 sq. in an ordinary workday.
  - Weather has improved since early summer, and crews are still starting early in the morning.

- **Upcoming Look Ahead:**
  - Metal coping installation.
  - Complete new drain tie-in and insulation.
  - Metal Pergola Installation.
  - Complete work on final classroom areas and move toward cafeteria and area ‘C’.
  - Standing seam metal to ship soon.
  - Masonry work over areas A and B.

Paul Laurence Dunbar High School – Roof Replacement

Area A & B – Tapered insulation installation and roofing adhesives.







Paul Laurence Dunbar High School – Roof Replacement

Various works around the site.







Paul Laurence Dunbar High School – Roof Replacement

Area B – Ventilator Flashing and cover board installation.





Paul Laurence Dunbar High School – Turf & Track Replacement

Completed/Work in Progress:

- Work on site is nearing completion. Site was walked on Monday. Some outstanding issues to still be addressed.
- Fence installation continues. Most posts have been installed.
- The striping for the track appears complete.
- Expansion joints in walks to be caulked and cleaned.

Upcoming Look Ahead:

- Finish fence installation.
- Cleanup of site/staging areas.
- Remediation of items to be addressed following site evaluations.
- Complete exterior building signage

Paul Laurence Dunbar High School – Turf & Track Replacement

Asphalt work is nearly complete





Paul Laurence Dunbar High School – Turf & Track Replacement

Fencing is nearly complete.





Paul Laurence Dunbar High School – Turf & Track Replacement

Newly striped track adjacent to new turf.

