

Lead in Drinking Water – Public and Nonpublic Schools

IMPORTANT NOTICE: ELEVATED WATER SAMPLE RESULT(S) **Cherry Hill Middle School**

ELEVATED LEAD WATER SAMPLE RESULT(S)

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations. On February 6, 2019, **one hundred (100)** lead water samples were collected from **Cherry Hill Middle School**. Of these lead water samples, **thirty (30)** had levels of lead exceeding the action level of 20 parts per billion (ppb) for lead in drinking water in school buildings. The elevated lead results from the sample(s) collected at Cherry Hill Middle were as follows:

24.2 parts per billion (ppb) **Kitchen bathroom sink**
109 parts per billion (ppb) **Room 120 (3rd from last sink on right side of room)**
56.2 parts per billion (ppb) **Room 120 (last sink on right side of room)**
30.9 parts per billion (ppb) **Room 120 (sink on left side of room)**
63.2 parts per billion (ppb) **Room 128 (sink in north east corner)**
26.4 parts per billion (ppb) **Room 128 (science storage closet)**
31.7 parts per billion (ppb) **Room 130 (left sink at west wall)**
65.1 parts per billion (ppb) **Room 130 (right sink at south wall)**
24.2 parts per billion (ppb) **Room 129 (right sink at north wall)**
55.2 parts per billion (ppb) **Room 129 (right sink at west wall)**
154 parts per billion (ppb) **Room 129 (left sink at west wall)**
23.5 parts per billion (ppb) **Room 129 (sink in south west corner)**
93.3 parts per billion (ppb) **Room 129 (right sink at east wall)**
84.0 parts per billion (ppb) **Room 129 (left sink at east wall)**
110 parts per billion (ppb) **Science storage closet between rooms 129/133**
435 parts per billion (ppb) **Room 131 (left sink at south wall)**
249 parts per billion (ppb) **Room 132 (right sink at west wall)**
8320 parts per billion (ppb) **Room 132 (middle/left sink at west wall)**
10800 parts per billion (ppb) **Room 132 (left sink at west wall)**
997 parts per billion (ppb) **Room 132 (sink in middle of room)**
23.5 parts per billion (ppb) **Room 132 (middle/right sink at west wall)**
59.6 parts per billion (ppb) **Room 133 (left sink at east wall)**
55.5 parts per billion (ppb) **Room 133 (middle/left sink at east wall)**
132 parts per billion (ppb) **Room 133 (middle/right sink at east wall)**
122 parts per billion (ppb) **Room 133 (right sink at east wall)**
1160 parts per billion (ppb) **Room 133 (sink in middle of room)**
7350 parts per billion (ppb) **Room 133 (right sink at north wall)**
262 parts per billion (ppb) **Room 133 (left sink at north wall)**
206 parts per billion (ppb) **Room 101 (right sink)**
35.4 parts per billion (ppb) **Room 101 (left sink)**

IMMEDIATE ACTIONS TAKEN

Results were received on April 9, 2019. A sign has been posted at each sink noted above, indicating that they are not to be used for consumption purposes.

NEXT STEPS

The sinks will continue to be used only for non-consumption purposes (e.g., hand washing) until remedial actions have taken place and follow up sampling shows results with levels below the action level.

ACTION LEVEL (AL)

The AL is 20 ppb for lead in drinking water in school buildings. The AL is the concentration of lead which, if exceeded, triggers required remediation.

HEALTH EFFECTS OF LEAD

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

SOURCES OF HUMAN EXPOSURE TO LEAD

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass fixtures, food, and cosmetics, exposure in the work place and exposure from certain hobbies, brass faucets, fittings, and valves. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead-containing water this may increase to 40 to 60 percent.

TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

Please note that boiling the water will not reduce lead levels.

ADDITIONAL INFORMATION

1. For additional information, please contact **Perry Willis, Executive Director for Support Services**, at **410-996-5400**. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at www.epa.gov/lead. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.



Cecil County Public Schools
201 Booth St.

Elkton, MD 21921

Attention: Andrew Curran

Report for Lab No: 40713.

Monday, April 8, 2019

Certificate of Analysis
AMENDED

Samples received by Martel from: Cherry Hill Middle School.

Project Identification: Water Analysis HB 270, sampled by Cecil County personnel.

February 6, 2019.

MARTEL NO.		CLIENT SAMPLE IDENTIFICATION			Sample Date/Time 02/06/2019 08:02	
40713	000001	22-BS-01: Boiler room bathroom				
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 15:40 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION			Sample Date/Time 02/06/2019 05:04	
40713	000002	22-DF-02: Cafeteria fountain				
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 15:52 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION			Sample Date/Time 02/06/2019 05:06	
40713	000003	22-KS-03: Kitchen (back, left corner)				
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		7.54	ug/l	EPA .200.8	2	03/25/2019 15:54 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION			Sample Date/Time 02/06/2019 05:06	
40713	000004	22-KS-04: Kitchen (back, left)				
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		2.95	ug/l	EPA .200.8	2	03/25/2019 15:57 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION			Sample Date/Time 02/06/2019 05:06	
40713	000005	22-KS-05: Kitchen (back, middle)				
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 15:59 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION			Sample Date/Time 02/06/2019 05:06	
40713	000006	22-KS-06: Kitchen (middle)				
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial

MARTEL NO. 40713 000006		CLIENT SAMPLE IDENTIFICATION 22-KS-06: Kitchen (middle)			Sample Date/Time 02/06/2019 05:06	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 16:02 BJ
MARTEL NO. 40713 000007		CLIENT SAMPLE IDENTIFICATION 22-KS-07: Kitchen (back, right)			Sample Date/Time 02/06/2019 05:06	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		4.98	ug/l	EPA .200.8	2	03/25/2019 16:04 BJ
MARTEL NO. 40713 000008		CLIENT SAMPLE IDENTIFICATION 22-BS-08: Kitchen bathroom			Sample Date/Time 02/06/2019 05:06	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		24.2	ug/l*	EPA .200.8	2	03/25/2019 16:07 BJ
MARTEL NO. 40713 000009		CLIENT SAMPLE IDENTIFICATION 22-CR-09: Room 120 (front to back, 1)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		12.8	ug/l	EPA .200.8	2	03/25/2019 16:09 BJ
MARTEL NO. 40713 000010		CLIENT SAMPLE IDENTIFICATION 22-CR-10: Room 120 (front to back, 2)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		13.4	ug/l	EPA .200.8	2	03/28/2019 01:07 BJ
MARTEL NO. 40713 000011		CLIENT SAMPLE IDENTIFICATION 22-CR-11: Room 120 (front to back, 3)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		8.34	ug/l	EPA .200.8	2	03/25/2019 16:22 BJ
MARTEL NO. 40713 000012		CLIENT SAMPLE IDENTIFICATION 22-CR-12: Room 120 (front to back, 4)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		109	ug/l*	EPA .200.8	2	03/25/2019 16:28 BJ
MARTEL NO. 40713 000013		CLIENT SAMPLE IDENTIFICATION 22-CR-13: Room 120 (front to back, 5)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		2.37	ug/l	EPA .200.8	2	03/25/2019 16:30 BJ



Certificate of Analysis

MARTEL NO. 40713 000014		CLIENT SAMPLE IDENTIFICATION 22-CR-14: Room 120 (front to back, 6)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		56.2	ug/l*	EPA .200.8	2	03/25/2019 16:33 BJ
MARTEL NO. 40713 000015		CLIENT SAMPLE IDENTIFICATION 22-CR-15: Room 120 (left)			Sample Date/Time 02/06/2019 05:12	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		30.9	ug/l*	EPA .200.8	2	03/25/2019 16:35 BJ
MARTEL NO. 40713 000016		CLIENT SAMPLE IDENTIFICATION 22-CR-16: Room 121			Sample Date/Time 02/06/2019 05:18	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		9.66	ug/l	EPA .200.8	2	03/25/2019 16:38 B J
MARTEL NO. 40713 000017		CLIENT SAMPLE IDENTIFICATION 22-BS-17: Mens bathroom near 121			Sample Date/Time 02/06/2019 05:17	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		13.5	ug/l	EPA .200.8	2	03/28/2019 01:09 BJ
MARTEL NO. 40713 000018		CLIENT SAMPLE IDENTIFICATION 22-BS-18: Womens bathroom near 122			Sample Date/Time 02/06/2019 05:17	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 16:43 B J
MARTEL NO. 40713 000019		CLIENT SAMPLE IDENTIFICATION 22-DF-19: Fountain outside bathrooms near stage			Sample Date/Time 02/06/201 9 05:22	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 16:45 BJ
MARTEL NO. 40713 000020		CLIENT SAMPLE IDENTIFICATION 22-BS-20: Girls bathroom near stage (right)			Sample Date/Time 02/06/201905:24	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		2.09	ug/l	EPA .200.8	2	03/25/2019 16:47 BJ
MARTEL NO. 40713 000021		CLIENT SAMPLE IDENTIFICATION 22-BS-21: Girls bathroom near stage (right, middle)			Sample Date/Time 02/06/201 9 05:24	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		3.3	ug/l	EPA .200.8	2	03/28/2019 01:12 BJ

MARTEL NO. 40713 000022		CLIENT SAMPLE IDENTIFICATION 22-BS-22: Girls bathroom near stage (left, middle)			Sample Date/Time 02/06/2019 05:24	
Compound		Test Value Test Unit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:03 BJ
MARTEL NO. 40713 000023		CLIENT SAMPLE IDENTIFICATION 22-BS-23: Girls bathroom near stage (left)			Sample Date/Time 02/06/2019 05:24	
Compound		Test Value TestUnit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:05 BJ
MARTEL NO. 40713 000024		CLIENT SAMPLE IDENTIFICATION 22-BS-24: Boys bathroom near stage (left)			Sample Date/Time 02/06/201 9 05:26	
Compound		Test Value Test Unit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:08 BJ
MARTEL NO. 40713 000025		CLIENT SAMPLE IDENTIFICATION 22-BS-25: Boys bathroom near stage (left, middle)			Sample Date/Time 02/06/2019 05:26	
Compound		Test Value Test Unit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:10 BJ
MARTEL NO. 40713 000026		CLIENT SAMPLE IDENTIFICATION 22-BS-26: Boys bathroom near stage (middle)			Sample Date/Time 02/06/201 9 05:26	
Compound		Test Value TestUnit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:13 BJ
MARTEL NO. 40713 000027		CLIENT SAMPLE IDENTIFICATION 22-BS-27: Boys bathroom near stage (right, middle)			Sample Date/Time 02/06/2019 05:26	
Compound		Test Value Test Unit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:15 BJ
MARTEL NO. 40713 000028		CLIENT SAMPLE IDENTIFICATION 22-BS-28: Boys bathroom near stage (right)			Sample Date/Time 02/06/2019 05:26	
Compound		Test Value Test Unit		Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2 ug/l		EPA .200.8	2	03/25/2019 17:18 BJ
MARTEL NO. 40713 000029		CLIENT SAMPLE IDENTIFICATION 22-CR-29: Room 124 (left)			Sample Date/Time 02/06/2019 05:29	
compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		6.83	ug/l	EPA .200.8	2	03/25/2019 17:20 BJ

MARTEL NO. 40713 000030		CLIENT SAMPLE IDENTIFICATION 22-CR-30: Room 124 (right)		Sample Date/Time 02/06/2019 05:29	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	8.0	ug/l	EPA .200.8	2	03/28/2019 01:14 BJ
MARTEL NO. 40713 000031		CLIENT SAMPLE IDENTIFICATION 22-OT-31: Work room by media center		Sample Date/Time 02/06/2019 05:30	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	2.38	ug/l	EPA .200.8	2	03/25/2019 17:33 BJ
MARTEL NO. 40713 000032		CLIENT SAMPLE IDENTIFICATION 22-BS-32: Womens bathroom near 126		Sample Date/Time 02/06/201 9 05:34	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	<2	ug/l	EPA .200.8	2	03/25/2019 17:38 BJ
MARTEL NO. 40713 000033		CLIENT SAMPLE IDENTIFICATION 22-BS-33: Mens bathroom near 127		Sample Date/Time 02/06/20 1 9 05:34	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	<2	ug/l	EPA .200.8	2	03/25/2019 17:40 BJ
MARTEL NO. 40713 000034		CLIENT SAMPLE IDENTIFICATION 22-DF-34: Fountain outside bathrooms near 118		Sample Date/Time 02/06/201 9 05:38	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	<2	ug/l	EPA .200.8	2	03/25/2019 17:43 BJ
MARTEL NO. 40713 000035		CLIENT SAMPLE IDENTIFICATION 22-BS-35: Girls bathroom near 118 (left)		Sample Date/Time 02/06/201 9 05:38	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	<2	ug/l	EPA .200.8	2	03/25/2019 17:46 BJ
MARTEL NO. 40713 000036		CLIENT SAMPLE IDENTIFICATION 22-BS-36: Girls bathroom near 118 (left, middle)		Sample Date/Time 02/06/201 9 05:38	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	<2	ug/l	EPA .200.8	2	03/25/2019 17:48 BJ
MARTEL NO. 40713 000037		CLIENT SAMPLE IDENTIFICATION 22-BS-37: Girls bathroom near 118 (middle)		Sample Date/Time 02/06/2019 05:38	
Compound	Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead	<2	ug/l	EPA .200.8	2	03/25/2019 17:51 BJ

MARTEL NO. 40713 000038		CLIENT SAMPLE IDENTIFICATION 22-BS-38: Girls bathroom near 118 (right, middle)			Sample Date/Time 02/06/201 9 05:38	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 17:53 BJ
MARTEL NO. 40713 000039		CLIENT SAMPLE IDENTIFICATION 22-BS-39: Girls bathroom near 118 (right)			Sample Date/Time 02/06/2019 05:38	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 17:56 BJ
MARTEL NO. 40713 000040		CLIENT SAMPLE IDENTIFICATION 22-BS-40: Boys bathroom near 118 (right)			Sample Date/Time 02/06/2019 05:40	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 17:58 BJ
MARTEL NO. 40713 000041		CLIENT SAMPLE IDENTIFICATION 22-BS-41: Boys bathroom near 118 (right, middle)			Sample Date/Time 02/06/2019 05:40	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 18:06 BJ
MARTEL NO. 40713 000042		CLIENT SAMPLE IDENTIFICATION 22-BS-42: Boys bathroom near 118 (middle)			Sample Date/Time 02/06/2019 05:40	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 18:13 BJ
MARTEL NO. 40713 000043		CLIENT SAMPLE IDENTIFICATION 22-BS-43: Boys bathroom near 118 (left, middle)			Sample Date/Time 02/06/2019 05:40	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 18:16 BJ
MARTEL NO. 40713 000044		CLIENT SAMPLE IDENTIFICATION 22-BS-44: Boys bathroom near 118 (left)			Sample Date/Time 02/06/2019 05:40	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 18:18 BJ
MARTEL NO. 40713 000045		CLIENT SAMPLE IDENTIFICATION 22-CR-45: Room 128 (south, right)			Sample Date/Time 02/06/201 9 05:00	
compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		non	operational	EPA .200.8	2	//



MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713	000046	22-CR-46: Room 128 (south, left)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2 //
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713	000047	22-CR-47: Room 128 (east, right)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2 //
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713	000048	22-CR-48: Room 128 (east, middle)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2 //
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:46	
40713	000049	22-CR-49: Room 128 (east, left)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		63.2	ug/l*	EPA .200.8	2 03/25/2019 18:21 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:46	
40713	000050	22-CR-50: Room 128 (north, teachers station)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		9.58	ug/l	EPA .200.8	2 03/25/2019 18:23 BJ
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713	000051	22-CR-51: Room 128 (west, right)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2 //
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713	000052	22-CR-52: Room 128 (west, left)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2 //
MARTEL NO.		CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:48	
40713	000053	22-CR-53: Room 128 (closet)			
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		26.4	ug/l*	EPA .200.8	2 03/25/2019 18:33 BJ

MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713 000054	22-CR-54: Room 130 (east, right)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	non	operational EPA .200.8	2	//
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713 000055	22-CR-55: Room 130 (east, left)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	non	operational EPA .200.8	2	//
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:50	
40713 000056	22-CR-56: Room 130 (north)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	9.40	ug/l	EPA .200.8	2 03/25/2019 18:38 BJ
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:50	
40713 000057	22-CR-57: Room 130 (west, right)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	13.6	ug/l	EPA .200.8	2 03/25/2019 18:41 BJ
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:50	
40713 000058	22-CR-58: Room 130 (west, middle)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	18.8	ug/l	EPA .200.8	2 03/28/2019 01:17 BJ
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:50	
40713 000059	22-CR-59: Room 130 (west, left)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	31.7	ug/l*	EPA .200.8	2 03/25/2019 18:46 BJ
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:50	
40713 000060	22-CR-60: Room 130 (south, right)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	65.1	ug/l*	EPA .200.8	2 03/25/2019 18:48 BJ
MARTEL NO.	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 05:00	
40713 000061	22-CR-61: Room 130 (south, left)			
Compound	Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead	non	operational EPA .200.8	2	//

MARTEL NO. 40713	000062	22-CR-62: Room 129 (north, right)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			24.2	ug/l*	EPA .200.8	2 03/25/2019 18:56 BJ
MARTEL NO. 40713	000063	22-CR-63: Room 129 (north, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			non	operational	EPA .200.8	2 //
MARTEL NO. 40713	000064	22-CR-64: Room 129 (west, right)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			55.2	ug/l*	EPA .200.8	2 03/25/2019 19:04 BJ
MARTEL NO. 40713	000065	22-CR-65: Room 129 (west, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			154	ug/l*	EPA .200.8	2 03/25/2019 19:06 BJ
MARTEL NO. 40713	000066	22-CR-66: Room 129 (south, right, front)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			23.5	ug/l*	EPA .200.8	2 03/25/2019 19:09 BJ
MARTEL NO. 40713	000067	22-CR-67: Room 129 (south, right, back)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			93.3	ug/l*	EPA .200.8	2 03/25/2019 19:11 BJ
MARTEL NO. 40713	000068	22-CR-68: Room 129 (south, middle)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			14.4	ug/l	EPA .200.8	2 03/25/2019 19:14 BJ
MARTEL NO. 40713	000069	22-CR-69: Room 129 (south, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound			Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead			84.0	ug/l*	EPA .200.8	2 03/25/2019 19:16 BJ

MARTEL NO. 40713 000070		CLIENT SAMPLE IDENTIFICATION 22-CR-70: Closet next to 133			Sample Date/Time 02/06/2019 06:03	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		110	ug/l*	EPA .200.8	2	03/25/2019 19:19 BJ
MARTEL NO. 40713 000071		CLIENT SAMPLE IDENTIFICATION 22-CR-71: Room 131 (west, left)			Sample Date/Time 02/06/2019 06:00	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		non	operational	EPA .200.8	2	//
MARTEL NO. 40713 000072		CLIENT SAMPLE IDENTIFICATION 22-CR-72: Room 131 (west, middle, left)			Sample Date/Time 02/06/2019 06:00	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		non	operational	EPA .200.8	2	//
MARTEL NO. 40713 000073		CLIENT SAMPLE IDENTIFICATION 22-CR-73: Room 131 (west, middle, right)			Sample Date/Time 02/06/2019 06:00	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		non	operational	EPA .200.8	2	//
MARTEL NO. 40713 000074		CLIENT SAMPLE IDENTIFICATION 22-CR-74: Room 131 (west, right)			Sample Date/Time 02/06/2019 06:00	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		non	operational	EPA .200.8	2	//
MARTEL NO. 40713 000075		CLIENT SAMPLE IDENTIFICATION 22-CR-75: Room 131 (middle of room)			Sample Date/Time 02/06/2019 06:05	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 19:29 BJ
MARTEL NO. 40713 000076		CLIENT SAMPLE IDENTIFICATION 22-CR-76: Room 131 (south, left)			Sample Date/Time 02/06/2019 06:07	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		435	ug/l*	EPA .200.8	2	03/25/2019 19:34 BJ
MARTEL NO. 40713 000077		CLIENT SAMPLE IDENTIFICATION 22-CR-77: Room 131 (south, right)			Sample Date/Time 02/06/2019 06:00	
Compound		Test Value Test Unit		Method	Detection Limit Analysis Date/Time/Initial	
Lead		non	operational	EPA .200.8	2	//



Certificate of Analysis

MARTEL NO. 40713	000078	22-CR-78: Room 132 (north, right)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound		Test Value	TestUnit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2	//
MARTEL NO. 40713	000079	22-CR-79: Room 132 (north, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:00	
Compound		Test Value	TestUnit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		non	operational EPA	.200.8	2	//
MARTEL NO. 40713	000080	22-CR-80: Room 132 (west, right)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:10	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		249	ug/l*	EPA .200.8	2	03/25/2019 19:36 BJ
MARTEL NO. 40713	000081	22-CR-81: Room 132 (west, middle)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:10	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		8320	ug/l*	EPA .200.8	2	04/01/2019 17:52 BJ
MARTEL NO. 40713	000082	22-CR-82: Room 132 (west, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:10	
Compound		Test Value	TestUnit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		10800	ug/l*	EPA .200.8	2	04/01/2019 17:54 BJ
MARTEL NO. 40713	000083	22-CR-83: Room 133 (east, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	TestUnit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		59.6	ug/l*	EPA .200.8	2	03/25/2019 19:44 BJ
MARTEL NO. 40713	000084	22-CR-84: Room 133 (east, middle, left)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	TestUnit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		55.5	ug/l*	EPA .200.8	2	03/25/2019 19:52 B J
MARTEL NO. 40713	000085	22-CR-85: Room 133 (east, middle, right)	CLIENT SAMPLE IDENTIFICATION		Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	TestUnit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		132	ug/l*	EPA .200.8	2	03/25/2019 19:54 BJ



Certificate of Analysis

MARTEL NO. 40713 000086		CLIENT SAMPLE IDENTIFICATION 22-CR-86: Room 133 (east, right)			Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		122.0	ug/l*	EPA .200.8	2	03/28/2019 01:20 BJ
MARTEL NO. 40713 000087		CLIENT SAMPLE IDENTIFICATION 22-CR-87: Room 133 (middle of room)			Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		1160	ug/l*	EPA .200.8	2	03/25/2019 19:59 BJ
MARTEL NO. 40713 000088		CLIENT SAMPLE IDENTIFICATION 22-CR-88: Room 133 (north, right)			Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		7350	ug/l*	EPA .200.8	2	04/01/2019 17:57 BJ
MARTEL NO. 40713 000089		CLIENT SAMPLE IDENTIFICATION 22-CR-89: Room 133 (north, left)			Sample Date/Time 02/06/2019 06:15	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		262	ug/l*	EPA .200.8	2	03/25/2019 20:02 BJ
MARTEL NO. 40713 000090		CLIENT SAMPLE IDENTIFICATION 22-DF-90: Girls locker room fountain			Sample Date/Time 02/06/2019 06:19	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 20:04 BJ
MARTEL NO. 40713 000091		CLIENT SAMPLE IDENTIFICATION 22-BS-91: Girls locker room bathroom (right)			Sample Date/Time 02/06/2019 06:19	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 20:14 BJ
MARTEL NO. 40713 000092		CLIENT SAMPLE IDENTIFICATION 22-BS-92: Girls locker room bathroom (left)			Sample Date/Time 02/06/2019 06:19	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 20:20 BJ
MARTEL NO. 40713 000093		CLIENT SAMPLE IDENTIFICATION 22-BS-93: Girls PE office bathroom			Sample Date/Time 02/06/2019 06:19	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		3.25	ug/l	EPA .200.8	2	03/25/2019 20:22 BJ

MARTEL NO. 40713 000094		CLIENT SAMPLE IDENTIFICATION 22-BS-94: Boys PE office bathroom		Sample Date/Time 02/06/2019 06:22	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		3.20	ug/l	EPA .200.8	2 03/25/2019 20:25 BJ
MARTEL NO. 40713 000095		CLIENT SAMPLE IDENTIFICATION 22-DF-95: Boys locker room fountain		Sample Date/Time 02/06/2019 06:22	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 20:27 BJ
MARTEL NO. 40713 000096		CLIENT SAMPLE IDENTIFICATION 22-BS-96: Boys locker room bathroom		Sample Date/Time 02/06/2019 06:22	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 20:30 BJ
MARTEL NO. 40713 000097		CLIENT SAMPLE IDENTIFICATION 22-DF-97: Fountain outside of gym near 116		Sample Date/Time 02/06/2019 06:22	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 20:32 BJ
MARTEL NO. 40713 000098		CLIENT SAMPLE IDENTIFICATION 22-BS-98: Womens bathroom near 114		Sample Date/Time 02/06/2019 06:24	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 20:35 BJ
MARTEL NO. 40713 000099		CLIENT SAMPLE IDENTIFICATION 22-BS-99: Mens bathroom near 115		Sample Date/Time 02/06/2019 06:24	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		2.16	ug/l	EPA .200.8	2 03/25/2019 20:37 BJ
MARTEL NO. 40713 000100		CLIENT SAMPLE IDENTIFICATION 22-BS-100: Main entry womens bathroom (left)		Sample Date/Time 02/06/2019 06:27	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		2.74	ug/l	EPA .200.8	2 03/25/2019 20:40 BJ
MARTEL NO. 40713 000101		CLIENT SAMPLE IDENTIFICATION 22-BS-101: Main entry womens bathroom (right)		Sample Date/Time 02/06/2019 06:27	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 20:48 BJ

MARTEL NO. 40713 000102		CLIENT SAMPLE IDENTIFICATION 22-BS-102: Main entry mens bathroom			Sample Date/Time 02/06/2019 06:27	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 20:55 BJ
MARTEL NO. 40713 000103		CLIENT SAMPLE IDENTIFICATION 22-DF-103: Main entry fountain			Sample Date/Time 02/06/2019 06:28	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 20:58 BJ
MARTEL NO. 40713 000104		CLIENT SAMPLE IDENTIFICATION 22-BS-104: Nurses office womens bathroom			Sample Date/Time 02/06/2019 06:32	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 21:00 BJ
MARTEL NO. 40713 000105		CLIENT SAMPLE IDENTIFICATION 22-BS-105: Nurses office mens bathroom			Sample Date/Time 02/06/2019 06:32	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2	03/25/2019 21:03 BJ
MARTEL NO. 40713 000106		CLIENT SAMPLE IDENTIFICATION 22-CR-106: Room 105			Sample Date/Time 02/06/2019 06:33	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		13.9	ug/l	EPA .200.8	2	03/25/2019 21:06 BJ
MARTEL NO. 40713 000107		CLIENT SAMPLE IDENTIFICATION 22-CR-107: Room 102 (left)			Sample Date/Time 02/06/2019 06:35	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		7.17	ug/l	EPA .200.8	2	03/25/2019 21:08 BJ
MARTEL NO. 40713 000108		CLIENT SAMPLE IDENTIFICATION 22-CR-108: Room 102 middle)			Sample Date/Time 02/06/2019 06:35	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		3.66	ug/l	EPA .200.8	2	03/25/2019 21:11 BJ
MARTEL NO. 40713 000109		CLIENT SAMPLE IDENTIFICATION 22-CR-109: Room 102 (right)			Sample Date/Time 02/06/2019 06:35	
Compound		Test Value	Test Unit	Method	Detection Limit	Analysis Date/Time/Initial
Lead		9.48	ug/l	EPA .200.8	2	03/25/2019 21:13 BJ

MARTEL NO. 40713 000110		CLIENT SAMPLE IDENTIFICATION 22-DF-110: Room 101 (right)		Sample Date/Time 02/06/2019 06:36	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 21:16 BJ
MARTEL NO. 40713 000111		CLIENT SAMPLE IDENTIFICATION 22-CR-111: Room 101 (middle, right)		Sample Date/Time 02/06/2019 06:36	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		206	ug/l*	EPA .200.8	2 03/25/2019 21:26 BJ
MARTEL NO. 40713 000112		CLIENT SAMPLE IDENTIFICATION 22-CR-112: Room 101 (middle, left)		Sample Date/Time 02/06/2019 06:36	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		8.37	ug/l	EPA .200.8	2 03/25/2019 21:31 BJ
MARTEL NO. 40713 000113		CLIENT SAMPLE IDENTIFICATION 22-CR-113: Room 101 (left)		Sample Date/Time 02/06/2019 06:36	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		35.4	ug/l*	EPA .200.8	2 03/25/2019 21:34 BJ
MARTEL NO. 40713 000114		CLIENT SAMPLE IDENTIFICATION 22-CR-114 Room 132(middle of room)		Sample Date/Time 02/06/2019 06:10	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		23.5	ug/l*	EPA .200.8	2 03/25/2019 21:36 BJ
MARTEL NO. 40713 000115		CLIENT SAMPLE IDENTIFICATION 22-CR-115 Room 132(west,middle,r)		Sample Date/Time 02/06/2019 06:10	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		997	ug/l*	EPA .200.8	2 04/01/2019 18:00 BJ
MARTEL NO. 40713 000116		CLIENT SAMPLE IDENTIFICATION 22-BS-116 Mens bathroom near 107		Sample Date/Time 02/06/2019 06:31	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		2.76	ug/l	EPA .200.8	2 03/25/2019 21:39 BJ
MARTEL NO. 40713 000117		CLIENT SAMPLE IDENTIFICATION 22-BS-117 Womens bathroom near 107		Sample Date/Time 02/06/2019 06:31	
Compound		Test Value	Test Unit	Method	Detection Limit Analysis Date/Time/Initial
Lead		<2	ug/l	EPA .200.8	2 03/25/2019 21:41 BJ

Certificate of Analysis

Martel Laboratories_{JDS} Inc.

1025 Cromwell Bridge Road - Baltimore, Maryland 21286
PH 410-825-7790 FAX 410-821-1054 EMAIL: martel@martellabs.com

CECILS

Page 16 OF 16

04/08/2019

stdl.frx

Notes and references:

40CFR136=U.S. "Code of Federal Regulations", Title 40, Protection of the Environment, Part 136, Guidelines Establishing Test Procedures for the Analysis of Pollutants Under the Clean Water Act.

* Results exceed 20.5 ug/l.

All samples tested were in acceptable condition, unless otherwise noted.
The results presented herein relate only to the samples or items tested.


Project Manager