Paul Laurence Dunbar High School – Roof Replacement

- **Completed/Work in Progress:**
  - Penthouse sloped roofing is 75% complete.
  - High wall flashing installation largely complete over areas A and B.
  - Classroom areas are 100% Based In.
  - Cafeteria is 20% Based In.

- **Upcoming Look Ahead:**
  - Continue work on cafeteria wing.
  - Cap sheet over remaining classroom areas.
  - Raising gas lines on MAU over cafeteria.
  - Edge metal and flashing tie ins.


Paul Laurence Dunbar High School – Roof Replacement

SBS Installation over Cafeteria wing.



Paul Laurence Dunbar High School – Roof Replacement

Newly ‘based in’ SBS system over classroom areas.




Paul Laurence Dunbar High School – Roof Replacement

New high wall and mechanical flashing at penthouse screen wall.



Paul Laurence Dunbar High School – Roof Replacement

¾ of sloped insulation areas next to penthouses have been ‘based in’.



Paul Laurence Dunbar High School – Roof Replacement

New materials storage and disposal area near loading dock.



Paul Laurence Dunbar High School – Roof Replacement

Various works around cafeteria wing.



Paul Laurence Dunbar High School – Roof Replacement

Completed SBS roofing besides edge work (foreground) with based in sections (back right).



Paul Laurence Dunbar High School – Roof Replacement

New roofing on the right side of photo meets ‘Area C’ on the left.

