

Lead in School Drinking Water Report

Columbia Junior High School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2026-03-12

Date(s) analyzed: 2026-03-24, 2026-03-26

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	419080	2026-03-12	Main Building	Pot Filler	Kitchen	1 of 3	Tap	center	170
2	419083	2026-03-12	Main Building	Sink	Kitchen	3 of 3	Tap	center	109
3	419086	2026-03-12	Main Building	Sink	Snack Bar	1 of 1	Sprayer	center	23
4	419085	2026-03-12	Main Building	Sink	Snack Bar	1 of 1	Tap	center	19
5	419084	2026-03-12	Main Building	Sink	Kitchen	3 of 3	Sprayer	center	18
6	419082	2026-03-12	Main Building	Sink - Multi-compartment	Kitchen	2 of 3	Sprayer	center	3
7	419088	2026-03-12	Main Building	Sink - Multi-compartment	Staff Lounge	1 of 1	Tap	center	1
8	419081	2026-03-12	Main Building	Sink - Multi-compartment	Kitchen	2 of 3	Tap	center	<1
9	419087	2026-03-12	Main Building	Sink	Nurses Office	1 of 1	Tap	center	<1
10	419089	2026-03-12	Main Building	Sink	Library Office	1 of 1	Tap	center	<1
11	419090	2026-03-12	Main Building	Sink	Room 207	1 of 2	Tap	left	<1
12	419091	2026-03-12	Main Building	Sink	Room 207	2 of 2	Tap	center	<1
13	419092	2026-03-12	Main Building	Fountain	Choir 205	1 of 1	Water Fountain	right	<1

.	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
14	419093	2026-03-12	Main Building	Fountain - Multi-level	Cafeteria	1 of 1	Water Fountain	right	<1
15	419094	2026-03-12	Main Building	Fountain - Multi-level	Cafeteria	1 of 1	Water Fountain	left	<1
16	419095	2026-03-12	Main Building	Fountain - Multi-level	Gym Foyer	1 of 1	Water Fountain	right	<1
17	419096	2026-03-12	Main Building	Fountain - Multi-level	Gym Foyer	1 of 1	Water Fountain	left	<1
18	419097	2026-03-12	Main Building	Fountain	Girls Locker Room	1 of 1	Water Fountain	right	<1
19	419098	2026-03-12	Main Building	Fountain - Multi-level	Weight Room	1 of 1	Water Fountain	right	<1
20	419099	2026-03-12	Main Building	Ice Machine	Training Room	1 of 1	Ice Machine	center	<1