Paul Laurence Dunbar High School – Roof Replacement

- **Completed/Work in Progress:**
  - Coping installation has begun.
  - Work in progress on penthouse buildings.
  - High wall flashing is underway.
  - Classroom cap sheet installation nearly complete.

- **Upcoming Look Ahead:**
  - Cap sheet over remaining classroom and cafeteria areas.
  - Continue work on sheet metal coping.
  - Continue flashing and curb work.
  - Begin work over area ‘C’.

Paul Laurence Dunbar High School – Roof Replacement

Curb installations over cafeteria area.



Paul Laurence Dunbar High School – Roof Replacement

Science wing being prepared to receive coping.



Paul Laurence Dunbar High School – Roof Replacement


A largely finished section of roofing over the library area.



Paul Laurence Dunbar High School – Roof Replacement

Various works around the site.







Paul Laurence Dunbar High School – Roof Replacement

Penthouse screen wall assembly with new roofing.



Paul Laurence Dunbar High School – Roof Replacement

Thru wall flashing and masonry work in progress at penthouse screen wall.



Paul Laurence Dunbar High School – Roof Replacement

Cap sheet strips at roof edge cleat detail.



Paul Laurence Dunbar High School – Roof Replacement

Close up of coping installation.

