
Paul Laurence Dunbar High School – Roof Replacement

- **Completed/Work in Progress:**
  - Areas A and B are fully based-in.
  - Gymnasium roof in the process of being torn off and based in, about 50% so far.


- **Upcoming Look Ahead:**
  - Continue work over Gymnasium Areas.
  - Return to Cafeteria wing for cap sheet once materials continue to arrive.
  - Coping and sheet metal installation.
  - Cap sheet on Gymnasium.

Paul Laurence Dunbar High School – Roof Replacement

New SBS system installation over gym.







Paul Laurence Dunbar High School – Roof Replacement

Staging area outside Gymnasium.



Paul Laurence Dunbar High School – Roof Replacement

Mushroom head ventilator over Gymnasium.



Paul Laurence Dunbar High School – Roof Replacement

Materials stored on Gymnasium Roof.



Paul Laurence Dunbar High School – Roof Replacement

High angle shot of Cafeteria Wing (left) and classroom wing (right) with flashing in foreground.



Paul Laurence Dunbar High School – Roof Replacement

Lighting and carts (left) used for installing insulation, cover board and base sheet (right).





Paul Laurence Dunbar High School – Roof Replacement

Weather Barrier Installation at Penthouse Walls



Paul Laurence Dunbar High School – Roof Replacement

Old meeting new roofing over Gymnasium.

