

Morris School District Board of Education Meeting



September 28, 2026

Morristown High School Learning Commons




Board of Education Staff Recognition



Mr. Brian DiDomenico
Morristown High School Foreman



Board of Education Staff Recognition



Hillcrest School Cleanest School Award

BOARD OF EDUCATION MEETING

September 28, 2026

Buildings & Grounds Department

Summer 2026

Capital Improvements

A comprehensive update on facility upgrades and infrastructure progress completed across the Morris School District during Summer 2026.

Mr. Glenn Miller

Director of Facilities



Morristown High School



Morristown High School



- **Auditorium Stage Lighting**
 - Replaced wiring, added 2 stations, 16 LED fixtures & control panel
 - Cuts ongoing equipment rentals & establishes baseline for future referendum renovation
- **AUX Gym Roof Restoration**
 - High-performance coating delivers a 20-year warranty at 50% of replacement cost
 - Solves long-standing leaks with minimal labor impact
- **Main Hallway Refresh (Around AUX Gym)**
 - Full cosmetic and lighting overhaul of the AUX gym corridor
 - Installed new floor tile, replacement ceiling tiles, and fresh paint throughout
 - Upgraded to high-efficiency LED flat panel lighting



MHS Hallway - Before



MHS Hallway - After



MHS Roof-In Progress



MHS Roof - After



**MHS Ceiling Tile & Lights
Before**



**MHS Ceiling Tile & Lights
After**





MHS Auditorium Lights

Frelinghuysen Middle School



Frelinghuysen Middle School



- **2nd Floor Art Room Renovations**

- Upgraded floors in 2 out of 3 rooms
- Upgraded ceiling tiles and lighting in all rooms
- Installed new modern cabinetry

- **2nd Floor Hallway & Stairwells**

- Fresh paint applied throughout the entire 2nd floor main corridor
- Refreshed all 3 connecting stairwells for a cohesive, clean look

- **Bus Loop Paved**

- **New Basketball Back Stops**

- Installed new back stops in Old Gym and added electric automated rising of the baskets

- **New Synthetic Turf Field**



ART HAS THE POWER TO CHANGE
THE WORLD

Room
#213

DEWALT

FMS Old Art Room



FMS Old Art Room



FMS Old Art Room



FMS New Art Room



FMS New Art Room



FMS New Art Room



FMS New Art Room



FMS 2nd Floor Hallway Before



FMS 2nd Floor Hallway - Before



FMS 2nd Floor Hallway - After



FMS 2nd Floor Hallway - After



FMS Corridor – After



FMS – Basketball Backstops



FMS Pavement Work In Progress



**FMS Pavement Work
After**



**FMS Turf Field
In Progress**



**FMS Turf Field
In Progress**

FMS New Turf Field Cutting Ceremony





FMS New Turf Field



FMS New Turf Field



FMS New Turf Field

Alexander Hamilton Elementary School



Alexander Hamilton School



- **Security Vestibule**
 - In progress and is slated to be finished mid-October.



Security Vestibule Doors

Alfred Vail Elementary School



Alfred Vail School



- **Cafeteria Windows**
 - Installed new wall of windows outside of Cafeteria
- **Painted Hallways**
 - 1st floor complete; 2nd floor in progress



NO
PARKING
FIRE
LANE

110

Alfred Vail School Windows



Alfred Vail Cafeteria Windows



Alfred Vail Cafeteria Windows



Alfred Vail Painted Hallways



Alfred Vail Painted Hallways

Hillcrest Elementary School



Hillcrest Elementary School




Critical Electrical Infrastructure Upgrades

- Full replacement of Boiler Room panel and Main Office sub-panel.
- Eliminated single-point-of-failure risk that threatened an entire wing outage.
- Replaced unserviceable, obsolete components with modern, code-compliant equipment.



**Hillcrest Electrical Panel -
Before/In Progress**





**Hillcrest School
Electrical Panel - After**



**Hillcrest
Sink Replacement**

Lafayette Learning Center



Lafayette Learning Center




- **Interior & Facility Upgrades**

- Completed safe asbestos abatement in Rooms 105 A, B, and C.
- Renovated and updated the Teachers' Lunchroom.
- Replaced manual portable sinks with permanent plumbing in 2 classrooms.

- **Grounds, Safety & Accessibility**

- Repaired sidewalk trip hazards along the walkway to the playground.
- Installed a new handicap-accessible swing on the playground.



LLC Sidewalk Repair



Renovated Teachers' Room



**Handicap Accessible
Swing - In Progress**



**Handicap Accessible
Swing - In Progress**



**Handicap Accessible
Swing - In Progress**



**Classroom Sink
Replacement**

Sussex Avenue Elementary School



Sussex Avenue Elementary School



- **Asbestos Tile Abatement & Full Replacement:** Safe removal and full re-tiling of the main hallway
- **Furniture Upgrades:** Installation of modern student furniture



Sussex Ave Floors - Before



Sussex Ave Floors - After



**Sussex Avenue Classroom
Floors - Before**






**Sussex Avenue Classroom
Floors - During**



**Sussex Avenue Classroom
Floors - After**



**Sussex Avenue Classroom
Brand New Student Desks**

Thomas Jefferson Elementary School



Thomas Jefferson Elementary School



- **Drainage Infrastructure**


- Trenching and new pipe installation completed to permanently resolve long-term storm drain flooding in the parking lot.

- **Facility Maintenance & Aesthetics**

- Performed floor tile repairs across high-traffic areas.
- Removed outdated hallway bulletin boards to declutter and refresh common spaces.



**Thomas Jefferson
Redone Drainage Trench**



Thomas Jefferson Hallways

Woodland Elementary School



Woodland Elementary School



- **Classroom Flooring**

- Full tile replacement completed in 1 classroom.
- 1 classroom postponed after asbestos testing came back positive. Abatement will be scheduled for the November break to avoid timeline disruption.

- **Grounds & Curb Appeal**

- Completed landscaping enhancements along the front walkway.

A wide-angle shot of a classroom floor. The floor is covered in a new, white, glossy vinyl material. Several long, rectangular green stripes are applied to the floor, likely for safety or organizational purposes. In the background, there are rows of black metal-framed chairs with wooden seats. To the right, there is a blue storage unit or desk area with various items on it, including a white air purifier or heater unit. The overall scene is bright and clean.

Woodland School Classroom Replacement Flooring

Idcats ROAR
ful, Outstanding, Accepting, Responsible



R

WOODLAND
ELEMENTARY

**Woodland School Main
Entrance -Before**

es ROAR
ng, Accepting, Responsible



R

WOODLAND
ELEMENTARY

**Woodland School Main
Entrance - After**



Thank You