Districtwide Lead in Drinking Water
Sampling and Remediation Plan for 2026-2028 Compliance.

Irvington UFSD

September 2026

Enviroscience Project #27912

ENVIROSCIENCE CONSULTANTS
A Mainline Company
2150 Smithtown Ave., Suite 3, Ronkonkoma, NY 11779
T: 631.580.3191 • F: 631.580.3195 • W: envirohealth.org

DISTRICTWIDE LEAD IN DRINKING WATER SAMPLING AND REMEDIATION PLAN

2026-2028

SEPTEMBER 2026

ENVIROSCIENCE PROJECT #27912

Prepared for: IRVINGTON UFSD
6 Dows Lane
Irvington, New York 10533

Prepared by: ENVIROSCIENCE CONSULTANTS, LLC
2150 Smithtown Avenue
Ronkonkoma, New York 11779
(631) 580-3191

Project Manager: 
Casey Lee

TABLE OF CONTENTS

Section	Title
1.0	Executive Summary
2.0	Sampling Methodology
3.0	Initial Results

Appendices

Appendix A	Dows Lane Elementary School
Appendix B	Main Street School
Appendix C	Middle School/High School Campus

1.0 EXECUTIVE SUMMARY

The Irvington UFSD has developed their Lead in Drinking Water Sampling and Remediation Plan for the 2026-2028 compliance period, as required by the New York State Department of Health (Public Health Law Sections 1370-a and 1110, Subpart 67-4 Lead Testing in School Drinking Water).

In accordance with the regulation, this Lead Remediation Plan is prepared to identify locations deemed as Applicable Drinking Water Sources and report first draw sample results, to mitigate locations where sample results exceed 5 parts per billion, to identify locations deemed as Non-Applicable Water Sources, communicate this designation to building occupants, and to develop strategies for monitoring locations deemed Non-Applicable Water Sources to ensure building occupants do not consume water from these locations.

The following locations within the Irvington UFSD buildings have been deemed Applicable Drinking Water Sources by the administration:

1) Water fountains and bottle filling stations;
2) Kitchen water faucets and pot fillers used in food preparation;
3) Ice machines
4) Nurse's Office and Faculty Room sinks

First draw samples were collected from each of these locations within the district and analyzed by a New York State Department of Health ELAP certified laboratory. The chains of custody are available upon request. For results at or below 5 ppb, no further action is required until the 2029-2031 compliance period. For locations above 5 ppb, options include: second and third draw sample collection to determine source of lead, designation of the location as Non-Applicable Water Source, or permanent removal of the fixture from the location. In either case, the result was communicated by Enviroscience Consultants, and the fixture was shut off by the district immediately upon receipt of results.

The following locations within the Irvington UFSD buildings were deemed Non-Applicable Water Sources by the administration:

1) Science Laboratory sinks
2) Art Room sinks
3) Technical Classroom sinks
4) Other Classroom sinks
5) Bathroom sinks
6) Outside spigots not used for sports or gardening
7) Custodial Closet sinks
8) Mixed Valve sinks (or hot only)
9) Coach's Office and Locker Room Showers

In these cases, the Irvington UFSD staff have placed signs adjacent to the fixture to notify occupants that the water is not intended for consumption. To further support this protocol, the following management of the locations is required:

1) Science Laboratory sinks - communicate in writing with students that these locations are for science experiments and hand washing only, not for consumption. This is most easily accomplished by including this language in the laboratory safety paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective science teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

2) Art Room sinks - communicate in writing to students that these locations are for cleaning of art supplies and hand washing only, not for consumption. This is most easily accomplished by including this language in the course paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective art teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

3) Technical Classroom sinks - classrooms in this category often include wood shop or auto mechanics classrooms, where students are to hand wash after bathroom usage or activities as part of a regular hygiene program. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

4) Other Classroom sinks - classrooms in this category often include elementary classrooms, where students are to hand wash after bathroom usage or activities as part of a regular hygiene program. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

5) Bathroom sinks - in intermediate buildings, signage should be sufficient for communicating the concept of hand washing only. In elementary schools, if signs are to be posted, then personal hygiene should be integrated into curriculum to ensure students understand bathroom sinks are for hand washing only, and not consumption. Further, show what the signage looks like in bathrooms, so they learn to recognize its meaning. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

6) Outside spigots - all-weather signage and or a key operated fixture should be installed at each location. Further, spigots will have a special key maintained by the custodial staff to ensure that non-authorized persons do not fill sports coolers or use hoses for consumption. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

7) Custodial Closet sinks - these locations should be accessed by custodial personnel only and locked when not in use. Access to others should be restricted. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

8) Mixed Valve sinks (or hot only) – per Public Health Law Sections 1370-a and 1110, Subpart 67-4 Lead Testing in School Drinking Water mixed valve or hot water only sources are not required to be sampled. Signage is required for these sources. Signage should be sufficient for communicating the concept of hand washing only. In elementary schools, personal hygiene should be integrated into curriculum to ensure students understand bathroom sinks are for hand washing only, and not consumption. Further, show what the signage looks like so they learn to recognize its meaning. This

program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

9) Showers – Signs should be posted upon the entrance of the shower where easily seen. Further, an effort should be made to limit potential water damage. Staff should inspect the condition of signs regularly.

All locations deemed Non-Applicable, but do not have signs, should be taken offline until signs have been posted. Signs are suggested to have pictures that instruct for handwashing only, do not drink.

2.0 SAMPLING METHODOLOGY

In accordance with the regulation, Enviroscience Consultants, LLC performed initial water sampling at the Irvington UFSD buildings on September 23rd, 24th, and 25th, 2026. Samples were collected in wide-mouth 250 milliliter containers and were collected in the morning hours before the facilities opened. The water sources were not used for at least 8 hours and not more than 18 hours prior to sampling. Unique source numbers and designations were assigned to each source location. Unique sample identification numbers were assigned to each sample taken. The key to fixture type codes and source designations are shown below.

Code Key for Lead in Water					
Fixture Type Codes					
BF	Bottle Filler	SK	Sink	SS	Slop Sink
HB	Hose Bib	SL	Supply Line	V	Valve
IM	Ice Machine	SP	Spigot	WC	Water Cooler
OS	Other Source	SPY	Spray	WF	Water Fountain
PF	Pot Filler				
Source Designations					
App	Applicable	N/A	Non-Applicable		

3.0 INITIAL RESULTS

All water source locations in each of the school buildings were assessed. Water source locations identified as drinking water sources were considered Applicable, and first draw samples were collected. Water source locations identified as non-drinking water sources were considered Non-Applicable, and these locations were documented.

The results of the initial sampling and the use of signs warning against water use at Non-Applicable sources is documented in the School Water Outlet Inventory for each building.

All elevated locations should be taken off line until the remediation is completed. Any other drinking water sources in these buildings that were not functional at the time of initial sampling and have not been tested should be tested before returning to service. All locations deemed Non-Applicable, but do not have signs, should be taken offline until signs have been posted. Signs are suggested to have pictures that instruct for handwashing only, do not drink.

The following is a summary of results in parts per billion (ppb) of locations in the Irvington UFSD where first-draw sample results were found above 5 ppb:

Dows Lane Elementary School			
SAMPLE LOCATION	RESULT	SAMPLE DATE	REMARKS
No Exceedances			

Main Street School			
SAMPLE LOCATION	RESULT	SAMPLE DATE	REMARKS
No Exceedances			

Middle School/High School Campus			
SAMPLE LOCATION	RESULT	SAMPLE DATE	REMARKS
No Exceedances			

Appendix A

Dows Lane Elementary School

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1001-01	Gym Bubbler	WF	App	<1.0	9/25/2026	-	-	-	-
1001-02	Gym Bottle Filler	BF	App	<1.0	9/25/2026	-	-	-	-
1002-03	Supt Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1003-01	Custodian	SK	N/A		9/25/2026	-	-	-	Sign
1004-01	Café Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1004-02	Café Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1005-01	Kitchen 3-Bay Sink - Left	SK	App	<1.0	9/25/2026	-	-	-	-
1005-02	Kitchen 3-Bay Sink - Right	SK	App	<1.0	9/25/2026	-	-	-	-
1005-03	Kitchen 3-Bay Sink - Spray	SPY	App	<1.0	9/25/2026	-	-	-	-
1005-04	Kitchen 2-Bay Sink	SK	App	2.0	9/25/2026	-	-	-	-
1005-05	Kitchen 2-Bay Sink - Spray	SPY	App	2.0	9/25/2026	-	-	-	-
1005-06	Kitchen Handwash	SK	N/A		9/25/2026	-	-	-	Sign
1006-01	1st Floor Men's Faculty Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1006-02	1st Floor Men's Faculty Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1007-01	1st Floor Women's Faculty Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
2001-01	2nd Floor Women's Faculty Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
3001-01	3rd Floor Women's Faculty Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1008-01	Room 101 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1008-02	Room 101	SK	N/A		9/25/2026	-	-	-	Sign
1008-03	Room 101 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1009-01	Room 102 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1009-02	Room 102	SK	N/A		9/25/2026	-	-	-	Sign
1009-03	Room 102 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1010-01	Room 103 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1010-02	Room 103	SK	N/A		9/25/2026	-	-	-	Sign
1010-03	Room 103 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1011-01	Room 104 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1011-02	Room 104	SK	N/A		9/25/2026	-	-	-	Sign
1011-03	Room 104 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1012-01	Room 105 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1012-02	Room 105	SK	N/A		9/25/2026	-	-	-	Sign
1012-03	Room 105 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1013-01	Room 106 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1013-02	Room 106	SK	N/A		9/25/2026	-	-	-	Sign
1013-03	Room 106 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1014-01	Room 107 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1014-02	Room 107	SK	N/A		9/25/2026	-	-	-	Sign
1014-03	Room 107 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1015-01	Room 108 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1015-02	Room 108	SK	N/A		9/25/2026	-	-	-	Sign
1015-03	Room 108 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1016-01	Room 109 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1016-02	Room 109	SK	N/A		9/25/2026	-	-	-	Sign
1016-03	Room 109 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1017-01	Room 110 Teacher's Lounge	SK	App	2.0	9/25/2026	-	-	-	-
1018-01	Room 111 Bubbler	WF	N/A		9/25/2026	-	-	-	Non-Functional; Shut off
1018-02	Room 111	SK	App	<1.0	9/25/2026	-	-	-	-
1018-03	Room 111 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1019-01	Nurse's Office	SK	App	4.0	9/25/2026	-	-	-	-
1019-02	Nurse's Office Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1020-01	Room 112 Bubbler	WF	N/A		9/25/2026	-	-	-	Non-Functional; Shut off
1020-02	Room 112	SK	App	2.0	9/25/2026	-	-	-	-
1021-01	Room 115 PLTW Bubbler	WF	App	2.0	9/25/2026	-	-	-	-
1021-02	Room 115 PLTW	SK	App	1.0	9/25/2026	-	-	-	-

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1022-01	Library	SK	N/A		9/25/2026	-	-	-	Sign
1022-02	Library	SK	N/A		9/25/2026	-	-	-	Sign
1023-01	Library Bathroom East	SK	N/A		9/25/2026	-	-	-	Sign
1024-01	Library Bathroom West	SK	N/A		9/25/2026	-	-	-	Sign
1025-01	Room 126	SK	N/A		9/25/2026	-	-	-	Sign
1025-02	Room 126	SK	N/A		9/25/2026	-	-	-	Sign
1025-03	Room 126 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1025-04	Room 126 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1026-01	Room 127	SK	N/A		9/25/2026	-	-	-	Sign
1026-02	Room 127	SK	N/A		9/25/2026	-	-	-	Sign
1026-03	Room 127 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1026-04	Room 127 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1027-01	Room 128	SK	N/A		9/25/2026	-	-	-	Sign
1027-02	Room 128	SK	N/A		9/25/2026	-	-	-	Sign
1027-03	Room 128 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1027-04	Room 128 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1028-01	Room 129	SK	N/A		9/25/2026	-	-	-	Sign
1028-02	Room 129	SK	N/A		9/25/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1028-03	Room 129 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1028-04	Room 129 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1029-01	Room 130	SK	N/A		9/25/2026	-	-	-	Sign
1029-02	Room 130	SK	N/A		9/25/2026	-	-	-	Sign
1029-03	Room 130 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
1029-04	Room 130 Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
2002-01	2nd Floor Lobby Bubbler	WF	App	<1.0	9/25/2026	-	-	-	-
2002-02	2nd Floor Lobby	BF	App	<1.0	9/25/2026	-	-	-	-
2003-01	2nd Floor NW Boy's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
2003-02	2nd Floor NW Boy's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
2004-01	2nd Floor NW Girl's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
2004-02	2nd Floor NW Girl's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
2004-03	2nd Floor NW Girl's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1030-01	MPR Bubbler	WF	App	1.0	9/25/2026	-	-	-	-
1030-02	MPR Girl's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1030-03	MPR Girl's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1030-04	MPR Boy's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
1030-05	MPR Boy's Bathroom	SK	N/A		9/25/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
2005-01	Room 201 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2005-02	Room 201	SK	N/A		9/25/2026	-	-	-	Sign
2006-01	Room 202 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2006-02	Room 202	SK	N/A		9/25/2026	-	-	-	Sign
2007-01	Room 203 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2007-02	Room 203	SK	N/A		9/25/2026	-	-	-	Sign
2008-01	Hall Outside Room 203 Bubbler	WF	App	1.0	9/25/2026	-	-	-	-
2009-01	Room 204 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2009-02	Room 204	SK	N/A		9/25/2026	-	-	-	Sign
2010-01	Room 205 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2010-02	Room 205	SK	N/A		9/25/2026	-	-	-	Sign
2011-01	Room 206 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2011-02	Room 206	SK	N/A		9/25/2026	-	-	-	Sign
2012-01	Room 207 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2012-02	Room 207	SK	N/A		9/25/2026	-	-	-	Sign
2013-01	Room 208 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2013-02	Room 208	SK	N/A		9/25/2026	-	-	-	Sign
2014-01	Room 209 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
2014-02	Room 209	SK	N/A		9/25/2026	-	-	-	Sign
2015-01	Room 210 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2015-02	Room 210	SK	N/A		9/25/2026	-	-	-	Sign
2016-01	Room 211 Bubbler	WF	N/A		9/25/2026	-	-	-	Removed from Service
2016-02	Room 211	SK	N/A		9/25/2026	-	-	-	Sign
1031-01	DO Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
4001-01	Hose Bib North	HB	N/A		9/25/2026	-	-	-	Sign
4002-01	Hose Bib South	HB	N/A		9/25/2026	-	-	-	Sign
1032-01	1st Floor OW Custodial Slop Sink	SS	N/A		9/25/2026	-	-	-	Sign
2017-01	2nd Floor OW Custodial Slop Sink	SS	N/A		9/25/2026	-	-	-	Sign
1033-01	1st Floor NW Custodial Slop Sink	SS	N/A		9/25/2026	-	-	-	Sign
2018-01	2nd Floor NW Custodial Slop Sink	SS	N/A		9/25/2026	-	-	-	Sign
1030-06	MPR Custodial Slop Sink	SS	N/A		9/25/2026	-	-	-	Sign
1034-01	Custodial Slop Sink	SS	N/A		9/25/2026	-	-	-	Sign
4003-01	Outdoor Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
4003-02	Outdoor Bathroom	SK	N/A		9/25/2026	-	-	-	Sign
4004-01	Outdoor Bathroom Bubbler	WF	App	<1.0	9/25/2026	-	-	-	-
4004-02	Outdoor Bathroom Bottle Filler	BF	App	<1.0	9/25/2026	-	-	-	-

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

September 28, 2026

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Ave.
Ronkonkoma, NY, 11779

Project:	Irvington UFSD (Dows Lane Elementary School)
Project Address:	Dows Lane Elementary School
Report ID:	260925030-4336
Sample IDs:	260925030-368 - 260925030-386

New York Environmental is a NELAC accredited laboratory. Attached reported results meet the requirements of the NELAC standard unless otherwise noted.

Samples' analytical results relate only to the parameters tested for the samples received in the condition received by the laboratory, as noted on the Chain of Custody. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYSDOH ELAP Lab ID: 11510

NYE Report #: 260925030-4336

Date Collected:	25-Sep-26
Date Received:	25-Sep-26
Date Analyzed:	28-Sep-26

Analytical Method:	EPA 200.9
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
260925030-368	1	Gym Bubbler - WF; initial	0.001	<0.001	mg/L	
260925030-369	2	Gym Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925030-370	3	Kitchen 3 - Bay - Left - SK; initial	0.001	<0.001	mg/L	
260925030-371	4	Kitchen 3 - Bay - Right - SK; initial	0.001	<0.001	mg/L	
260925030-372	5	Kitchen 3 - Bay - Right Spray - SPY; initial	0.001	<0.001	mg/L	
260925030-373	6	Kitchen 2 - Bay - SK; initial	0.001	0.002	mg/L	
260925030-374	7	Kitchen 2 - Bay Spray - SPY; initial	0.001	0.002	mg/L	
260925030-375	8	Room 110 Teacher's Lounge - SK; initial	0.001	0.002	mg/L	
260925030-376	9	Room 111 - SK; initial	0.001	<0.001	mg/L	
260925030-377	10	Nurse's Office - SK; initial	0.001	0.004	mg/L	
260925030-378	11	Room 112 - SK; initial	0.001	0.002	mg/L	
260925030-379	12	Room 115 PLTW - SK; initial	0.001	0.001	mg/L	
260925030-380	13	Room 115 PLTW Bubbler - WF; initial	0.001	0.002	mg/L	
260925030-381	14	2nd Floor Lobby Bubbler - WF; initial	0.001	<0.001	mg/L	
260925030-382	15	2nd Floor Lobby Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925030-383	16	Hall by Room 203 Bubbler - WF; initial	0.001	0.001	mg/L	
260925030-384	17	MPR Bubbler - WF; initial	0.001	0.001	mg/L	
260925030-385	18	Outside Bathroom Bubbler - WF; initial	0.001	<0.001	mg/L	
260925030-386	19	Outside Bathroom Bottle Filler - BF; initial	0.001	<0.001	mg/L	

Comment(s):

LOQ: Limit of Quantitation
CID: Client ID

Appendix B

Main Street School

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1001-01	Gym Bottle Filler	BF	App	<1.0	9/23/2026	-	-	-	-
1001-02	Gym Bubbler	WF	App	<1.0	9/23/2026	-	-	-	-
1001-03	Gym Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1001-04	Gym Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1001-05	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1001-06	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1001-07	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
2001-01	Nurse's Office Exam Area	SK	App	<1.0	9/23/2026	-	-	-	-
2001-02	Nurse's Office Bathroom - Left	SK	App	<1.0	9/23/2026	-	-	-	-
2001-03	Nurse's Office Bathroom - Right	SK	App	<1.0	9/23/2026	-	-	-	-
2002-01	Custodian's Office	SK	N/A		9/23/2026	-	-	-	Sign
1002-01	1st Floor Custodial Slop Sink	SS	N/A		9/23/2026	-	-	-	Sign
1003-01	1st Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1003-02	1st Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1003-03	1st Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1004-01	1st Floor Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
1005-01	1st Floor Bubbler	WF	App	<1.0	9/23/2026	-	-	-	-
1005-02	1st Floor Bottle Filler	BF	App	<1.0	9/23/2026	-	-	-	-

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
2003-01	2nd Floor Custodial Slop Sink	SS	N/A		9/23/2026	-	-	-	Sign
2004-01	2nd Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
2004-02	2nd Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
2004-03	2nd Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
2005-01	2nd Floor Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
2005-02	2nd Floor Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
2006-01	2nd Floor Bubbler	WF	App	<1.0	9/23/2026	-	-	-	-
2006-02	2nd Floor Bottle Filler	BF	App	<1.0	9/23/2026	-	-	-	-
3001-01	3rd Floor Custodial Slop Sink	SS	N/A		9/23/2026	-	-	-	Sign
3002-01	3rd Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
3002-02	3rd Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
3002-03	3rd Floor Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
3003-01	3rd Floor Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
3003-02	3rd Floor Boy's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
3004-01	Room 304	SK	N/A		9/23/2026	-	-	-	Sign
3005-01	Room 306	SK	N/A		9/23/2026	-	-	-	Sign
1005-01	Kitchen Prep Area 3-Bay	SK	App	1.0	9/23/2026	-	-	-	-
1005-02	Kitchen Prep Area Handwash	SK	N/A		9/23/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
3006-01	PLTW	SK	N/A		9/23/2026	-	-	-	Sign
2007-01	Teacher's Lounge	SK	App	<1.0	9/23/2026	-	-	-	-
2007-02	Teacher's Lounge Spray	SPY	N/A		9/23/2026	-	-	-	Non-functional, Shut off
2007-03	Teacher's Lounge Ice Machine	IM	N/A		9/23/2026	-	-	-	Non-functional, Shut off
3007-01	3rd Floor Bubbler	WF	App	<1.0	9/23/2026	-	-	-	-
3007-02	3rd Floor Bottle Filler	BF	App	<1.0	9/23/2026	-	-	-	-
-	Art Room	SK	N/A		9/23/2026	-	-	-	Sign
-	Art Room	SK	N/A		9/23/2026	-	-	-	Sign
-	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
-	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
-	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
-	Gym Girl's Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
-	PE Bathroom	SK	N/A		9/23/2026	-	-	-	Sign
-	PE Shower	SPY	N/A		9/23/2026	-	-	-	Sign

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

September 24, 2026

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Ave.
Ronkonkoma, NY, 11779

Project:	Irvington UFSD
Project Address:	Main Street School
Report ID:	260923001-4290
Sample IDs:	260923001-014 - 260923001-026

New York Environmental is a NELAC accredited laboratory. Attached reported results meet the requirements of the NELAC standard unless otherwise noted.

Samples' analytical results relate only to the parameters tested for the samples received in the condition received by the laboratory, as noted on the Chain of Custody. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYSDOH ELAP Lab ID: 11510

NYE Report #: 260923001-4290

Date Collected:	23-Sep-26
Date Received:	23-Sep-26
Date Analyzed:	24-Sep-26

Analytical Method:	EPA 200.9
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
260923001-014	1	Nurse's Office Exam Area - SK; initial	0.001	<0.001	mg/L	
260923001-015	2	Nurse's Office Bathroom - Left - SK; initial	0.001	<0.001	mg/L	
260923001-016	3	Nurse's Office Bathroom - Right - SK; initial	0.001	<0.001	mg/L	
260923001-017	4	Teacher's Lounge - SK; initial	0.001	<0.001	mg/L	
260923001-018	5	2nd Floor Bubbler - WF; initial	0.001	<0.001	mg/L	
260923001-019	6	2nd Floor Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260923001-020	7	3rd Floor Bubbler - WF; initial	0.001	<0.001	mg/L	
260923001-021	8	3rd Floor Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260923001-022	9	1st Floor Bubbler - WF; initial	0.001	<0.001	mg/L	
260923001-023	10	1st Floor Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260923001-024	11	Kitchen / Prep Area 3-Bay - SK; initial	0.001	0.001	mg/L	
260923001-025	12	Gym Bubbler - WF; initial	0.001	<0.001	mg/L	
260923001-026	13	Gym Bottle Filler - BF; initial	0.001	<0.001	mg/L	

Comment(s):

LOQ: Limit of Quantitation
CID: Client ID

Appendix C

Middle School/High School Campus

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
CMS									
2001-01	Kitchen 2-Bay	SK	App	2.0	9/24/2026	-	-	-	-
2001-02	Kitchen 2-Bay Spray	SPY	App	<1.0	9/24/2026	-	-	-	-
2001-03	Kitchen 3-Bay Dishwash	SK	N/A		9/24/2026	-	-	-	Sign
2001-04	Kitchen Island	SK	App	<1.0	9/24/2026	-	-	-	-
2001-05	Kitchen Handwash	SK	N/A		9/24/2026	-	-	-	Sign
2001-06	Kitchen Deli Line Handwash	SK	N/A		9/24/2026	-	-	-	Sign
2001-07	Kitchen Ice Machine	IM	App	<1.0	9/24/2026	-	-	-	-
2002-01	Cafeteria Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
2002-02	Cafeteria Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
3001-01	3rd Floor Hallway Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
2003-01	2nd Floor Hallway Bubbler by S-201	WF	N/A		9/24/2026	-	-	-	Removed from Service
1001-01	1st Floor Hallway Bubbler by S-101	WF	App	<1.0	9/24/2026	-	-	-	-
1001-02	1st Floor Hallway Bottle Filler by S-101	BF	App	<1.0	9/24/2026	-	-	-	-
1002-01	1st Floor Hallway Bubbler by S-106	WF	N/A		9/24/2026	-	-	-	Removed from Service
1003-01	1st Floor Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1003-02	1st Floor Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1004-01	1st Floor Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1004-02	1st Floor Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1005-01	1st Floor Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
1006-01	1st Floor Custodial Closet	SS	N/A		9/24/2026	-	-	-	Sign
1007-01	S-101	SK	N/A		9/24/2026	-	-	-	Sign
1007-02	S-101	SK	N/A		9/24/2026	-	-	-	Sign
1007-03	S-101	SK	N/A		9/24/2026	-	-	-	Sign
1007-04	S-101	SK	N/A		9/24/2026	-	-	-	Sign
1007-05	S-101	SK	N/A		9/24/2026	-	-	-	Sign
1007-06	S-101	SK	N/A		9/24/2026	-	-	-	Sign
1008-01	S-102	SK	N/A		9/24/2026	-	-	-	Sign
1009-01	S-103	SK	N/A		9/24/2026	-	-	-	Sign
1009-02	S-103	SK	N/A		9/24/2026	-	-	-	Sign
1009-03	S-103	SK	N/A		9/24/2026	-	-	-	Sign
1009-04	S-103	SK	N/A		9/24/2026	-	-	-	Sign
1009-05	S-103	SK	N/A		9/24/2026	-	-	-	Sign
1009-06	S-103	SK	N/A		9/24/2026	-	-	-	Sign
1010-01	S-104	SK	N/A		9/24/2026	-	-	-	Sign
1010-02	S-104	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1010-03	S-104	SK	N/A		9/24/2026	-	-	-	Sign
1010-04	S-104	SK	N/A		9/24/2026	-	-	-	Sign
1010-05	S-104	SK	N/A		9/24/2026	-	-	-	Sign
1010-06	S-104	SK	N/A		9/24/2026	-	-	-	Sign
1011-01	S-105	SK	N/A		9/24/2026	-	-	-	Sign
1012-01	S-106	SK	N/A		9/24/2026	-	-	-	Sign
1012-02	S-106	SK	N/A		9/24/2026	-	-	-	Sign
1012-03	S-106	SK	N/A		9/24/2026	-	-	-	Sign
1012-04	S-106	SK	N/A		9/24/2026	-	-	-	Sign
1012-05	S-106	SK	N/A		9/24/2026	-	-	-	Sign
1012-06	S-106	SK	N/A		9/24/2026	-	-	-	Sign
2004-01	2nd Floor Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
2004-02	2nd Floor Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
2005-01	2nd Floor Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
2005-02	2nd Floor Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
2006-01	2nd Floor Custodial Closet	SS	N/A		9/24/2026	-	-	-	Sign
2007-01	S-201	SK	N/A		9/24/2026	-	-	-	Sign
2007-02	S-201	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
2007-03	S-201	SK	N/A		9/24/2026	-	-	-	Sign
2007-04	S-201	SK	N/A		9/24/2026	-	-	-	Sign
2007-05	S-201	SK	N/A		9/24/2026	-	-	-	Sign
2007-06	S-201	SK	N/A		9/24/2026	-	-	-	Sign
2008-01	S-202	SK	N/A		9/24/2026	-	-	-	Sign
2009-01	S-203	SK	N/A		9/24/2026	-	-	-	Sign
2009-02	S-203	SK	N/A		9/24/2026	-	-	-	Sign
2009-03	S-203	SK	N/A		9/24/2026	-	-	-	Sign
2009-04	S-203	SK	N/A		9/24/2026	-	-	-	Sign
2009-05	S-203	SK	N/A		9/24/2026	-	-	-	Sign
2009-06	S-203	SK	N/A		9/24/2026	-	-	-	Sign
2010-01	S-204	SK	N/A		9/24/2026	-	-	-	Sign
2010-02	S-204	SK	N/A		9/24/2026	-	-	-	Sign
2010-03	S-204	SK	N/A		9/24/2026	-	-	-	Sign
2010-04	S-204	SK	N/A		9/24/2026	-	-	-	Sign
2010-05	S-204	SK	N/A		9/24/2026	-	-	-	Sign
2010-06	S-204	SK	N/A		9/24/2026	-	-	-	Sign
2011-01	S-205	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
2012-01	2nd Floor Hallway Bubbler by S-206	WF	App	<1.0	9/24/2026	-	-	-	-
2013-01	S-206	SK	N/A		9/24/2026	-	-	-	Sign
2013-02	S-206	SK	N/A		9/24/2026	-	-	-	Sign
2013-03	S-206	SK	N/A		9/24/2026	-	-	-	Sign
2013-04	S-206	SK	N/A		9/24/2026	-	-	-	Sign
2013-05	S-206	SK	N/A		9/24/2026	-	-	-	Sign
2013-06	S-206	SK	N/A		9/24/2026	-	-	-	Sign
3002-01	3rd Floor Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
3003-01	3rd Floor Custodial Closet	SS	N/A		9/24/2026	-	-	-	Sign
3004-01	S-301	SK	N/A		9/24/2026	-	-	-	Sign
3004-02	S-301	SK	N/A		9/24/2026	-	-	-	Sign
3004-03	S-301	SK	N/A		9/24/2026	-	-	-	Sign
3004-04	S-301	SK	N/A		9/24/2026	-	-	-	Sign
3004-05	S-301	SK	N/A		9/24/2026	-	-	-	Sign
3004-06	S-301	SK	N/A		9/24/2026	-	-	-	Sign
3005-01	S-302	SK	N/A		9/24/2026	-	-	-	Sign
3006-01	S-303	SK	N/A		9/24/2026	-	-	-	Sign
3006-02	S-303	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
3006-03	S-303	SK	N/A		9/24/2026	-	-	-	Sign
3006-04	S-303	SK	N/A		9/24/2026	-	-	-	Sign
3006-05	S-303	SK	N/A		9/24/2026	-	-	-	Sign
3006-06	S-303	SK	N/A		9/24/2026	-	-	-	Sign
3007-01	S-304	SK	N/A		9/24/2026	-	-	-	Sign
3007-02	S-304	SK	N/A		9/24/2026	-	-	-	Sign
3007-03	S-304	SK	N/A		9/24/2026	-	-	-	Sign
3007-04	S-304	SK	N/A		9/24/2026	-	-	-	Sign
3007-05	S-304	SK	N/A		9/24/2026	-	-	-	Sign
3007-06	S-304	SK	N/A		9/24/2026	-	-	-	Sign
3008-01	S-305	SK	N/A		9/24/2026	-	-	-	Sign
3009-01	S-306	SK	N/A		9/24/2026	-	-	-	Sign
3009-02	S-306	SK	N/A		9/24/2026	-	-	-	Sign
3009-03	S-306	SK	N/A		9/24/2026	-	-	-	Sign
3009-04	S-306	SK	N/A		9/24/2026	-	-	-	Sign
3009-05	S-306	SK	N/A		9/24/2026	-	-	-	Sign
3009-06	S-306	SK	N/A		9/24/2026	-	-	-	Sign
1013-01	Ground Floor Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1013-02	Ground Floor Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1014-01	Boiler Room	SS	N/A		9/24/2026	-	-	-	Sign
1015-01	Facilities Garage	SS	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
High School									
1001-01	HS Garden Level Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1002-01	HS Garden Level Hallway Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1002-02	HS Garden Level Hallway Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1003-01	Marra Lounge Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
1004-01	Loading Dock Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
1005-01	GL Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1005-02	GL Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1006-01	GL Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1006-02	GL Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1007-01	Room H-018	SK	App	2.0	9/24/2026	-	-	-	-
1008-01	BOCES Nurse's Office	SK	App	3.0	9/24/2026	-	-	-	-
1009-01	Marra Lounge	SK	App	<1.0	9/24/2026	-	-	-	-
1010-01	1st Floor Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1010-02	1st Floor Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1011-01	1st Floor Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1011-02	1st Floor Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1012-01	Faculty Men's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1012-02	Faculty Men's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1013-01	Faculty Women's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1013-02	Faculty Women's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1014-01	Bathroom by Main Office	SK	N/A		9/24/2026	-	-	-	Sign
1015-01	Main Office Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1015-02	Main Office Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1016-01	1st Floor Hallway Bubbler by H-124	WF	App	<1.0	9/24/2026	-	-	-	-
1016-02	1st Floor Hallway Bottle Filler by H-124	BF	App	<1.0	9/24/2026	-	-	-	-
1017-01	Nurse's Office	SK	App	<1.0	9/24/2026	-	-	-	-
1017-02	Nurse's Office Bathroom	WF	App	<1.0	9/24/2026	-	-	-	-
2001-01	2nd Floor Hallway Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
2001-02	2nd Floor Hallway Bottle Filler	BF	App	<1.0	9/25/2026	-	-	-	-
2002-01	2nd Floor Bubbler by H-224	SK	App	<1.0	9/24/2026	-	-	-	-
2003-01	2nd Floor Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
2003-02	2nd Floor Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
2004-01	2nd Floor Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
2004-02	2nd Floor Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
Middle School									
1001-01	Nurse's Office	SK	App	<1.0	9/24/2026	-	-	-	-
1001-02	Nurse's Bathroom	SK	App	<1.0	9/24/2026	-	-	-	-
1002-01	A Wing Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1002-02	A Wing Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1003-01	1st Floor B Wing Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
1004-01	1st Floor Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1004-02	1st Floor Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1005-01	1st Floor Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
1005-02	1st Floor Girl's Bathroom - Center	SK	N/A		9/24/2026	-	-	-	Sign
1005-03	1st Floor Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1006-01	1st Floor Custodial Closet	SS	N/A		9/24/2026	-	-	-	Sign
1007-01	B Wing Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1007-02	B Wing Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1008-01	D Wing Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
2001-01	2nd Floor Boy's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
2001-02	2nd Floor Boy's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
2002-01	2nd Floor Girl's Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
2002-02	2nd Floor Girl's Bathroom - Center	SK	N/A		9/24/2026	-	-	-	Sign
2002-03	2nd Floor Girl's Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign
1009-01	C Wing Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1009-02	C Wing Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1010-01	D Wing Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1010-02	D Wing Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1011-01	Teacher's Lounge	SK	App	<1.0	9/24/2026	-	-	-	-

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
Theater/Gym									
1001-01	Main Lobby Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1001-02	Main Lobby Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1002-01	Boy's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1002-02	Boy's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1002-03	Boy's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1002-04	Boy's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1003-01	Girl's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1003-02	Girl's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1003-03	Girl's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1003-04	Girl's Bathroom Sink	SK	N/A		9/24/2026	-	-	-	Sign
1004-01	Stage Dressing Room	SK	N/A		9/24/2026	-	-	-	Sign
1004-02	Stage Dressing Room	SK	N/A		9/24/2026	-	-	-	Sign
1004-03	Stage Dressing Room	SS	N/A		9/24/2026	-	-	-	Sign
1005-01	Storage Room	SS	N/A		9/24/2026	-	-	-	Sign
1005-02	Storage Room Ice Machine	IM	App	<1.0	9/24/2026	-	-	-	-
1006-01	Boy's Coach's Office	SK	N/A		9/24/2026	-	-	-	Sign
1006-02	Boy's Coach's Office Shower	SPY	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1007-01	Hallway by Boy's Locker Room Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1008-01	Boy's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1008-02	Boy's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1008-03	Boy's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1008-04	Boy's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1008-05	Boy's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
1008-06	Boy's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
1008-07	Boy's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
1008-08	Boy's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
1009-01	Girl's Coach's Office	SK	N/A		9/24/2026	-	-	-	Sign
1009-02	Girl's Coach's Office Shower	SPY	N/A		9/24/2026	-	-	-	Sign
1010-01	Girl's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1010-02	Girl's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1010-03	Girl's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1010-04	Girl's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1010-05	Girl's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
1010-06	Girl's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
1010-07	Girl's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
1010-08	Girl's Locker Room Showers	SPY	N/A		9/24/2026	-	-	-	Sign
2001-01	2nd Floor Lobby Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1011-01	Gym Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1011-02	Gym Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1011-03	Gym Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
LGA									
1001-01	Library Hallway Right Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1002-01	Library Hallway Left Bubbler	WF	App	<1.0	9/24/2026	-	-	-	-
1002-02	Library Hallway Left Bottle Filler	BF	App	<1.0	9/24/2026	-	-	-	-
1003-01	Gym Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1003-02	Gym Bubbler	WF	N/A		9/24/2026	-	-	-	Removed from Service
1004-01	Boy's Coach's Bathroom	SK	N/A		9/24/2026	-	-	-	Sign
1004-02	Boy's Coach's Shower	SPY	N/A		9/24/2026	-	-	-	Sign
1005-01	Boy's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1005-02	Boy's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1006-01	Girl's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1006-02	Girl's Locker Room	SK	N/A		9/24/2026	-	-	-	Sign
1007-01	Girl's Coach's Bathroom	SK	N/A		9/24/2026	-	-	-	Sign

Fixture #	Sample Location	Fixture Type	App or N/A	Latest 1st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remarks
CLP									
4001-01	Concession Outdoor Bubbler - Side	WF	App	<1.0	9/24/2026	-	-	-	-
4001-02	Concession Outdoor Bottle Filler - Side	WF	App	<1.0	9/24/2026	-	-	-	-
4002-01	Concession Outdoor Cooler Hose	HB/OS	N/A		9/24/2026	-	-	-	Non-functional; Locked with Water Key
4003-01	Concession Outdoor Bubbler - Front	WF	App	<1.0	9/24/2026	-	-	-	-
4003-02	Concession Outdoor Bottle Filler - Front	BF	App	<1.0	9/24/2026	-	-	-	-
4004-01	Concession	SK	App	<1.0	9/24/2026	-	-	-	-
4004-02	Concession Handwash	SK	N/A		9/24/2026	-	-	-	Sign
4004-03	Concession Ice Machine	IM	App	<1.0	9/24/2026	-	-	-	-
4004-04	Concession Slop Sink	SS	N/A		9/24/2026	-	-	-	Sign
4005-01	Concession Bathroom - Left	SK	N/A		9/24/2026	-	-	-	Sign
4005-02	Concession Bathroom - Right	SK	N/A		9/24/2026	-	-	-	Sign

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

September 28, 2026

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Ave.
Ronkonkoma, NY, 11779

Project:	Irvington UFSD (Irvington Middle / High School Campus)
Project Address:	Irvington Middle / High School Campus
Report ID:	260925031-4337
Sample IDs:	260925031-433 - 260925031-478

New York Environmental is a NELAC accredited laboratory. Attached reported results meet the requirements of the NELAC standard unless otherwise noted.

Samples' analytical results relate only to the parameters tested for the samples received in the condition received by the laboratory, as noted on the Chain of Custody. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYSDOH ELAP Lab ID: 11510

NYE Report #: 260925031-4337

Date Collected:	24-Sep-26
Date Received:	25-Sep-26
Date Analyzed:	28-Sep-26

Analytical Method:	EPA 200.9
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
260925031-433	1	HS - Garden Level Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-434	2	HS - Garden Level Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-435	3	HS - 2nd Floor Hallway Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-436	4	HS - 2nd Floor Hallway Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-437	5	HS - 2nd Floor Bubbler by H-224 - WF; initial	0.001	<0.001	mg/L	
260925031-438	6	CMS - Cafeteria Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-439	7	CMS - Cafeteria Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-440	8	CMS - Kitchen 2-Bay - SK; initial	0.001	0.002	mg/L	
260925031-441	9	CMS - Kitchen 2-Bay Sprayer - SPY; initial	0.001	<0.001	mg/L	
260925031-442	10	CMS - Kitchen Ice Machine - IM; initial	0.001	<0.001	mg/L	
260925031-443	11	CMS - Kitchen Island - SK; initial	0.001	<0.001	mg/L	
260925031-444	12	CMS - 2nd Floor Hall Bubbler by S206 - WF; initial	0.001	<0.001	mg/L	
260925031-445	13	CMS - 1st Floor Hall Bubbler by S101 - WF; initial	0.001	<0.001	mg/L	
260925031-446	14	CMS - 1st Floor Hall Bottle Filler by S101 - BF; initial	0.001	<0.001	mg/L	
260925031-447	15	HS - 1st Floor Hall Bubbler by H124 - WF; initial	0.001	<0.001	mg/L	
260925031-448	16	HS - 1st Floor Hall Bottle Filler by H124 - BF; initial	0.001	<0.001	mg/L	
260925031-449	17	HS - Nurse's Office - SK; initial	0.001	<0.001	mg/L	
260925031-450	18	HS - Nurse's Office Bathroom - SK; initial	0.001	<0.001	mg/L	
260925031-451	19	HS - Main Office Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-452	20	HS - Main Office Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-453	21	LGA - Library Hall Left Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-454	22	LGA - Library Hall Left Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-455	23	Middle School - B Wing Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-456	24	Middle School - B Wing Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-457	25	Middle School - A Wing Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-458	26	Middle School - A Wing Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-459	27	Middle School - Nurse's Office - SK; initial	0.001	<0.001	mg/L	
260925031-460	28	Middle School - Nurse's Office Bathroom - SK; initial	0.001	<0.001	mg/L	
260925031-461	29	Middle School - D Wing Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-462	30	Middle School - D Wing Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-463	31	Middle School - Teacher's Lounge - SK; initial	0.001	<0.001	mg/L	
260925031-464	32	Middle School - C Wing Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-465	33	Middle School - C Wing Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-466	34	Theater/Gym - Hall by Boy's Locker Rm - WF; initial	0.001	<0.001	mg/L	

NYE Report #: 260925031-4337

Date Collected:	24-Sep-26
Date Received:	25-Sep-26
Date Analyzed:	28-Sep-26

Analytical Method:	EPA 200.9
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
260925031-467	35	Theater/Gym - Storage Ice Machine - IM; initial	0.001	<0.001	mg/L	
260925031-468	36	Theater/Gym - Main Lobby Bubbler - WF; initial	0.001	<0.001	mg/L	
260925031-469	37	Theater/Gym - Main Lobby Bottle Filler - BF; initial	0.001	<0.001	mg/L	
260925031-470	38	CLP - Outdoor Bubbler - Front - WF; initial	0.001	<0.001	mg/L	
260925031-471	39	CLP - Outdoor Bottle Filler - Front - BF; initial	0.001	<0.001	mg/L	
260925031-472	40	CLP - Outdoor Bubbler - Side - WF; initial	0.001	<0.001	mg/L	
260925031-473	41	CLP - Outdoor Bottle Filler - Side - BF; initial	0.001	<0.001	mg/L	
260925031-474	42	CLP - Concession Sink - SK; initial	0.001	<0.001	mg/L	
260925031-475	43	CLP - Ice Machine - IM; initial	0.001	<0.001	mg/L	
260925031-476	44	HS - Marra Lounge - SK; initial	0.001	<0.001	mg/L	
260925031-477	45	HS - Room H-018 - SK; initial	0.001	0.002	mg/L	
260925031-478	46	HS - BOCES Nurse's Office - SK; initial	0.001	0.003	mg/L	

Comment(s):

LOQ: Limit of Quantitation
CID: Client ID