Paul Laurence Dunbar High School – Roof Replacement

- **Completed/Work in Progress:**
  - Areas A and B are fully based-in.
  - Gymnasium roof in the process of being torn off and based in, about 50% so far.

- **Upcoming Look Ahead:**
  - Continue work over Gymnasium Areas.
  - Return to Cafeteria wing for cap sheet as roofing materials continue to arrive.
  - Coping and sheet metal installation.
  - Cap sheet on Gymnasium.


Paul Laurence Dunbar High School – Roof Replacement


Overall shot of work in progress.



Paul Laurence Dunbar High School – Roof Replacement

New SBS coping base in over gym and existing sheet metal drainage lip at canopy.





Paul Laurence Dunbar High School – Roof Replacement

Base in areas awaiting cap sheet over cafeteria.



Paul Laurence Dunbar High School – Roof Replacement

Penthouse area awaiting cap sheet next to capped classroom wing.



Paul Laurence Dunbar High School – Roof Replacement

Partially based-in gymnasium roof.



Paul Laurence Dunbar High School – Roof Replacement

Old roofing over gymnasium meeting new SBS base-in.



Paul Laurence Dunbar High School – Roof Replacement

Auditorium area will be based-in after gymnasium area.



Paul Laurence Dunbar High School – Roof Replacement

Aerial shot looking towards area ‘C’ (in progress).

