Paul Laurence Dunbar High School – Roof Replacement

- **Completed/Work in Progress:**
  - Base-In is 99% Complete
  - Auditorium is based in and next to receive cap sheet.
  - Additional cap sheet materials delivered to site.

- **Upcoming Look Ahead:**
  - Masonry thru wall work on area ‘C’.
  - Complete cap sheet over areas ‘A’ and ‘B’, including areas adjacent to penthouses.
  - Edge metal installation.
  - Gutters and downspouts.
  - Standing seam delivery.

Paul Laurence Dunbar High School – Roof Replacement

Work in progress over area ‘C’.



Paul Laurence Dunbar High School – Roof Replacement

Part of area ‘A’ awaiting cap sheet (left).



Paul Laurence Dunbar High School – Roof Replacement

Close-up of auditorium deck with sound attenuation.





Paul Laurence Dunbar High School – Roof Replacement

Auditorium with tarp protection over audience area.



Paul Laurence Dunbar High School – Roof Replacement

New SBS sheet delivered to the site and ready for installation.



Paul Laurence Dunbar High School – Roof Replacement

SBS crew working on auditorium area



Paul Laurence Dunbar High School – Roof Replacement

SBS crew doing demolition work overnight on area ‘C’.



Paul Laurence Dunbar High School – Roof Replacement

Insulation mechanically fastened to the deck at area ‘C’.

