Lead Tests - Ruch Elementary School - Cafeteria/Gymnasium/Media Center/Rooms 5-6 - # 20481100											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481100-006KF	20481100-006KF21A	Kitchen Food Prep - Sink (Left)	09/23/26	4.3						NRC Copper/Lead Test Site
2	20481100-007KF	20481100-007KF21A	Kitchen Food Prep/Eyewash - Sink (Right)	09/23/26	8.8						NRC Copper/Lead Test Site
3	20481100-013KF	20481100-013KF21A	Kitchen - Sink (Pre-rinse/Dishwsher)	09/23/26	0.9						
4	20481100-008KF	20481100-008KF21A	Kitchen - Sink (Hand Wash)	10/13/26	0.9						
5	20481100-009BF	20481100-009BF21A	Kitchen Unisex Restroom - Sink	09/23/26	1.7	Lead	03/02/20	04/22/21	Pantair F1B1-RC	Ferguson	
6	20481100-005DW	20481100-005DW21A	Gym - Drinking Fountain	09/23/26	ND	Lead	10/01/23	10/01/23	Elkay		
7			Gym - Bottle Filler	09/23/26	ND	Lead	10/01/23	10/01/23	Elkay		Discovered 9/23/2026
8	20481100-014BF	20481100-014BF21A	Gym - Boy's Locker Room Right Side Of The Stage - Sink (L)	09/23/26	9.9	Lead	05/16/22	05/16/22	F1000-B1B-RC	Ferguson	
9	20481100-015BF	20481100-015BF21A	Gym - Boy's Locker Room Right Side Of The Stage - Sink (R)	09/23/26	11.3						
10	20481100-016BF	20481100-016BF21A	Gym - Girl's Locker Room Left Side Of The Stage - Sink (L)	09/23/26	4.4						
11	20481100-017BF	20481100-017BF21A	Gym - Girl's Locker Room Left Side Of The Stage - Sink (R)	09/23/26	4.9						
12	20481100-001DW	20481100-001DW21A	Media Center Work Room - Drinking Fountain	09/23/26	7.6						
13	20481100-002SF	20481100-002SF21A	Media Center Work Room - Sink	09/23/26	11.9						
14	20481100-018DW	New number	Room 5 - Drinking Fountain	09/23/26	1.6						New Jan 2025
15	20481100-019CF	New number	Room 5 - Sink	09/23/26	2.8						New Jan 2025
16	20481100-003DW	20481100-003DW21A	Computer Room - Drinking Fountain - DELETED	01/16/20	N/A	Lead	01/01/06	04/26/21	3US-MAX-F01H	Lowes	Removed - Commputer Room is now room 5
17	20481100-004CF	20481100-004CF21A	Computer Room - Sink - DELETED	01/16/20	N/A	Lead	01/01/06	04/26/21	3US-MAX-F01H	Lowes	Removed - Commputer Room is now room 5
18	20481100-010DW	20481100-010DW21A	Room 6 - Drinking Fountain	09/23/26	8.1						
19	20481100-011CF	20481100-011CF21A	Room 6 - Sink	09/23/26	5.7	Lead	03/19/19	04/26/21	3US-MAX-F01H	Lowes	
20	20481100-012DW	20481100-012DW21A	Outside Room 6 - Drinking Fountain	09/23/26	1.2	Lead	07/20/16	04/26/21	3US-MAX-F01H	Lowes	NRC Copper/Lead Test Site
Lead Tests - Ruch Elementary School - Rooms 10-13 Building - # 20481101											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481101-001DW	20481101-001DW21A	Room 10 - Drinking Fountain	09/23/26	5.9						
2	20481101-002CF	20481101-002CF21A	Room 10 - Sink	09/23/26	2.1	Lead	03/19/19	04/26/21	3US-MAX-F01H	Lowes	
3	20481101-003DW	20481101-003DW21A	Room 11 - Drinking Fountain	09/23/26	2.6						
4	20481101-004CF	20481101-004CF21A	Room 11 - Sink	09/23/26	3.6						
5	20481101-005DW	20481101-005DW21A	Room 12 - Drinking Fountain	09/23/26	4.1						
6	20481101-006CF	20481101-006CF21A	Room 12 - Sink	09/23/26	3.7						
7	20481101-007DW	20481101-007DW21A	Outside Room 13 - Drinking Fountain	09/23/26	2.7						NRC Copper/Lead Test Site
8	20481101-008DW	20481101-008DW21A	Room 13 - Drinking Fountain	09/23/26	2.3						
9	20481101-009CF	20481101-009CF21A	Room 13 - Sink	09/23/26	12.5						
Lead Tests - Ruch Elementary School - Rooms 7-9 Building - # 20481102											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481102-001DW	20481102-001DW21A	Room 7 - Drinking Fountain	09/23/26	11.9						
2	20481102-002CF	20481102-002CF21A	Room 7 - Sink	09/23/26	5.7						
3	20481102-003DW	20481102-003DW21A	Room 8 - Drinking Fountain	09/23/26	6.8						
4	20481102-004CF	20481102-004CF21A	Room 8 - Sink	09/23/26	7.7						
5	20481102-005DW	20481102-005DW21A	Room 9 - Drinking Fountain	09/23/26	5.5	Lead	01/26/20	04/26/21	3US-MAX-F01H	Lowes	
6	20481102-006CF	20481102-006CF21A	Room 9 - Sink	09/23/26	9.9						
7	20481102-007BF	20481102-007BF21A	Boy's Restroom Outside Room 9 - Sink	09/23/26	5.0						
8	20481102-008BF	20481102-008BF21A	Girl's Restroom Outside Room 9 - Sink	09/23/26	10.7						

Lead Tests - Ruch Elementary School - Rooms 2-4 Building - # 20481103											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481103-001BF	20481103-001BF21A	Staff Restroom Outside The Main Office - Sink	09/23/26	2.2						
2	20481103-002DW	20481103-002DW21A	Room 2 - Drinking Fountain	09/23/26	4.6						NRC Copper/Lead Test Site
3	20481103-003CF	20481103-003CF21A	Room 2 - Sink	09/23/26	0.7	Lead	01/26/20	04/26/21	3US-MAX-F01H	Lowes	
4	20481103-004DW	20481103-004DW21A	Room 3 - Drinking Fountain	09/23/26	10.7						
5	20481103-005CF	20481103-005CF21A	Room 3 - Sink	09/23/26	3.7						
6	20481103-006DW	20481103-006DW21A	Room 4 - Drinking Fountain	09/23/26	7.4						
7	20481103-007CF	20481103-007CF21A	Room 4 - Sink	09/23/26	7.4						
Lead Tests - Ruch Elementary School - Main Office Building - # 20481104											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481104-001NS	20481104-001NS21A	Health Room - Sink	09/23/26	4.5						
2	20481104-002BF	20481104-002BF21A	Health Room Restroom - Sink	09/23/26	5.0	Lead	10/31/24	10/31/24	3M	Ferguson	
3	20481104-003DW	20481104-003DW21A	Sports Field - Drinking Fountain (On Wellhouse #2) - DELETED	09/23/26	N/A						Oct 2026 Fixture Removed
Lead Tests - Ruch Elementary School - Front Restrooms Building - # 20481105											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481105-001DW	20481105-001DW21A	Outside Main Office - Drinking Fountain (Left)	09/23/26	ND						NRC Copper/Lead Test Site (old)
2	20481105-002DW	20481105-002DW21A	Outside Main Office - Drinking Fountain (Right)	09/23/26	ND						
3	20481105-003BF	20481105-003BF21A	Boy's Restroom Adjacent To Main Office - Sink (Left)	09/23/26	5.7						
4	20481105-004BF	20481105-004BF21A	Boy's Restroom Adjacent To Main Office - Sink (Right)	09/23/26	2.9						
5	20481105-005BF	20481105-005BF21A	Boy's Restroom Adjacent To Main Office - Sink (Center)	09/23/26	ND						
6	20481105-006BF	20481105-006BF21A	Boy's Restroom (Unisex Area) Adjacent To Main Office - Sink	10/13/26	ND						
7	20481105-007BF	20481105-007BF21A	Girl's Restroom Adjacent To Main Office - Sink (Left)	09/23/26	5.1						
8	20481105-008BF	20481105-008BF21A	Girl's Restroom Adjacent To Main Office - Sink (Right)	09/23/26	6.6						
9	20481105-009BF	20481105-009BF21A	Girl's Restroom Adjacent To Main Office - Sink (Center)	09/23/26	ND						
10	20481105-010BF	20481105-010BF21A	Girl's Restroom (Unisex Area) Adjacent To Main Office - Sink	10/13/26	ND						
Lead Tests - Ruch Elementary School - Staff Break Room Building - # 20481106											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481106-001SF	20481106-001SF21A	Staff Break Room - Sink	09/23/26	ND						
2	20481106-002SF	20481106-002SF21A	Room Adjacent To Staff Break Room - Sink	09/23/26	6.4	Lead	08/05/16	04/26/21	3US-MAX-F01H	Lowes	
N/A	N/A	N/A	Staff Break Room - Drinking Fountain - DELETED	06/30/16	N/A						Removed
Lead Tests - Ruch Elementary School - Rooms 14-15 - # 20481107											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filter For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481107-001DW	20481107-001DW21A	Room 15 - Drinking Fountain	10/13/26	0.5	Lead	03/02/20	10/12/26	Pantair F1B1-RC	Ferguson	
2	20481107-002CF	20481107-002CF21A	Room 15 - Sink	09/23/26	2.6	Lead	03/19/19	01/31/23	3US-MAX-F01H	Lowes	
3	20481107-003DW	20481107-003DW21A	Room 14 - Drinking Fountain	09/23/26	7.0	Lead	03/02/20	04/22/21	Pantair F1B1-RC	Ferguson	
4	20481107-004CF	20481107-004CF21A	Room 14 - Sink	09/23/26	9.4	Lead	03/02/20	04/22/21	Pantair F1B1-RC	Ferguson	

*None Detected (ND) = 0.10 Or Less PPB

= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 10 parts per billion (PPB) (As of July 2026)

*The E.P.A.'s recommended action level for lead in schools is 20 PPB. Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400.

*In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB). Now 10 PPB in July 2026.

*The E.P.A. action level for copper is 1.30 mg/L

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.