Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
#123 Prep Room Sink	20810200-001OT	09/24/26	ND
#S3 Classroom S. Sink E. Faucet	20810200-002CF	09/24/26	ND
#S3 Classroom S. Sink W. Faucet	20810200-003CF	09/24/26	ND
#S3 Classroom N. Sink E. Faucet	20810200-004CF	09/24/26	0.129
#S3 Classroom N. Sink W. Faucet	20810200-005CF	09/24/26	ND
#S3 Classroom Ctr. Sink	20810200-006CF	09/24/26	ND
#156 HS Girls Restrm S. Sink S. Fct	20810200-007BF	09/24/26	1.23
#156 HS Girls Restrm S. Sink N. Fct	20810200-008BF	09/24/26	0.616
#156 HS Girls Restrm N. Sink N. Fct	20810200-009BF	09/24/26	ND
#156 HS Girls Restrm N. Sink S. Fct	20810200-010BF	09/24/26	0.356
#155 HS Boys Restrm N. Sink N. Fct	20810200-011BF	09/24/26	0.853
#155 HS Boys Restrm N. Sink S. Fct	20810200-012BF	09/24/26	0.826
#155 HS Boys Restm S. Sink N. Fct	20810200-013BF	09/24/26	0.422
#155 HS Boys Restrm S. Sink S. Fct	20810200-014BF	09/24/26	0.555
#101 MS Upper Drink Fountain	20810200-015DW	09/24/26	ND
#101 MS Lower Drink Fountain	20810200-016DW	09/24/26	ND
#102 HS Upper Drink Fountain	20810200-017DW	09/24/26	ND
#102 HS Lower Drink Fountain	20810200-018DW	09/24/26	ND
#129 Staff Men’s Restrm E. Sink	20810200-019BF	09/24/26	ND
#129 Staff Men’s Restrm W. Sink	20810200-020BF	09/24/26	ND
#S1 Classroom S. Sink E Faucet	20810200-021CF	09/24/26	ND
#S1 Classroom S. Sink W. Faucet	20810200-022CF	09/24/26	ND
#S1 Classroom N. Sink E. Faucet	20810200-023CF	09/24/26	ND
#S1 Classroom N. Sink W. Faucet	20810200-024CF	09/24/26	ND
#S1 Classroom Ctr. Sink	20810200-025CF	09/24/26	ND
#S2 Classroom S. Sink E. Faucet	20810200-026CF	09/24/26	ND
#S2 Classroom S. Sink W. Faucet	20810200-027CF	09/24/26	ND
ND = Not Dectected - Lead level is below the set detection limits of .1 ppb			

Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
#S2 Classroom N. Sink E. Faucet	20810200-028CF	09/24/26	ND
#S2 Classroom N. Sink W. Faucet	20810200-029CF	09/24/26	ND
#S2 Classroom Ctr. Sink	20810200-030CF	09/24/26	ND
#125 Staff Women's Restrm E. Sink	20810200-031BF	09/24/26	ND
#125 Staff Women's Restrm W. Sink	20810200-032BF	09/24/26	ND
#127 Prep Room Sink	20810200-033OT	09/24/26	ND
#S4 Classroom E. Sink	20810200-034CF	09/24/26	ND
#S4 Classroom W. Sink	20810200-035CF	09/24/26	ND
ND = Not Dectected - Lead level is below the set detection limits of .1 ppb			