Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
#S5 Classroom E. Sink	20810200-036CF	9/25/2026	ND
#S5 Classroom W. Sink	20810200-037CF	9/25/2026	ND
#153 MS Boys Restrm N. Sink N. Fct	20810200-038BF	9/25/2026	0.217
#153 MS Boys Restrm N. Sink S. Fct	20810200-039BF	9/25/2026	0.556
#153 MS Boys Restrm S. Sink N. Fct	20810200-040BF	9/25/2026	0.183
#153 MS Boys Restrm S. Sink S. Fct	20810200-041BF	9/25/2026	0.826
#154 MS Girls Restrm N. Sink N. Fct	20810200-042BF	9/25/2026	0.197
#154 MS Girls Restrm N. Sink S. Fct	20810200-043BF	9/25/2026	0.146
#154 MS Girls Restrm S. Sink N. Fct	20810200-044BF	9/25/2026	0.243
#101 MS Water Bottle Filler	20810200-056WB	9/25/2026	ND
#102 HS Water Bottle Filler	20810200-057WB	9/25/2026	ND
#154 MS Girls Restrm S. Sink S. Fct	20810200-058BF	9/25/2026	0.117
Band Room (#34) Sink	20810202-001CF	9/25/2026	0.34
Band Room (#34) DF	20810202-002DW	9/25/2026	ND
Choir Rm (#35) Bottle Filler	20810202-003WB	9/25/2026	1.76
Choir Rm (#35) DF	20810202-004DW	9/25/2026	1.81
Canteen Food Prep Sink	20810201-001KF	9/25/2026	ND
Gym Commons Drinking Fountain	20810201-002DW	9/25/2026	0.435
Boys Locker Rm Restroom W. Sink	20810201-004BF	9/25/2026	0.192
Boys Locker Rm Restroom Ctr. Sink	20810201-005BF	9/25/2026	ND
Boys Locker Rm Restroom E. Sink	20810201-006BF	9/25/2026	0.144
Girls Team Rm Restroom Sink	20810201-008BF	9/25/2026	0.454
Girls Locker Rm Restroom S. Sink	20810201-010BF	9/25/2026	0.489
Girls Locker Rm Restroom Ctr. Sink	20810201-011BF	9/25/2026	0.563
Girls Locker Rm Restroom N. Sink	20810201-012BF	9/25/2026	0.139
Girls Locker Rm Drinking Fountain	20810201-013DW	9/25/2026	ND
Girls Lckr Rm Coach's Restrm Sink	20810201-014BF	9/25/2026	0.253
ND = Not Dectected - Lead level is below the set detection limits of .1 ppb			

Water Testing Results - Pleasant Hill School District
Action Level is 15 parts per billion (ppb)

Fixture Location / Description	Fixture ID #	Test Date	Test Results (ppb)
Girls Restroom N. Sink	20810201-015BF	09/25/26	ND
Girls Restroom S. Sink	20810201-016BF	09/25/26	ND
Boys Restroom N. Sink	20810201-017BF	09/25/26	0.522
Boys Restroom S. Sink	20810201-018BF	09/25/26	0.465
Weight Room Drinking Fountain	20810201-019DW	09/25/26	0.344
Girls Locker Rm Bottle Filler	20810201-021WB	09/25/26	ND
Gym Commons Water Bottle Filler	20810201-052WB	09/25/26	ND
Boys Locker Rm Coach Sink	20810201-053SF	09/25/26	ND

ND = Not Dectected - Lead level is below the set detection limits of .1 ppb